

Project No: 22131

Project: Roughbirchworth Lodge
Roughbirchworth Lane
Oxspring
Barnsley
S36 8YZ

Subject: Road Condition Report

Date: 24th October 2023 (Issue 02)

BDI STRUCTURAL SOLUTIONS LTD

CONSULTING CIVIL AND
STRUCTURAL ENGINEERS

Suite B
Stafford Court
Washway Road
Sale

Tel 0161 969 3886
Website: www.bdistructuralsolutions.co.uk
Email: steve@bdistructuralsolutions.co.uk

1.0 GENERAL

This road condition report has been prepared to support the planning application. The location of the proposed development site can be seen in the image below.




Figure 1.0 – Location of Development

The site is currently occupied by several outbuildings, hardstandings and an open expanse of land including trees and shrubs.

2.0 ROAD CONDITION ASSESSMENT

2.1 Introduction

2.1.1 Project Brief

The road condition has been assessed for 240m along Roughbirchworth Lane. This is 50m southwest and 192m northeast of the main access for the proposed development. The location of the photographs can be seen partly below and in Appendix B.




Figure 2 – Photograph Location Plan

2.1.2 Existing Road Condition

Site photographs, taken on the 2nd December 2022 during a site reconnaissance, have been included in this report and the location can be found in Appendix B. The drawing includes a chainage from the centre of the proposed junction; northerly from Ch.0m to 192m and southerly from Ch.0m to -50m.

The condition of the road is described in detail below for each photograph.

No intrusive investigation was carried out for this report.

Ch.-50m to Ch.-28m (Images 01 to 07)

This location includes the junction between Roughbitchworth Lane and Tollbar Close. Image 01 shows crazing in the footpath surface layer and in addition, kerbs and road markings are in poor condition.



Image 01 – Chainage -50m



Image 02 – Chainage 45m

Image 03 also shows potholes forming along the junction tie-in construction joint and that pothole repair attempts have been carried out previously.



Image 03 – Chainage 40m

Image 04 shows several service trench infills with a variety of asphalt mixes and aggregate sizes.



Image 04 – Chainage 47m

Image 05 shows concrete gully surround failure including fretting and crazing of the surface layer.



Image 05 – Chainage 36m

Images 06 and 07 appear to show polishing of the surface course, possibly caused by excessive amounts of binder in the asphalt mix.



Image 06 – Chainage 35m



Image 07 – Chainage -28m

Ch. 23m (Image 08)

Image 08 reveals failing trench infill forming along the construction joint of the trench. The failure is likely due to non-application of sealant.



Image 08 – Chainage 23m

Ch. 38m (Image 09)

Image 09 reveals several patch repairs that are poorly constructed with potholes forming. The use of varying aggregates and no sealant has caused weakness in the surface layer. Road markings are in poor condition.



Image 09 – Chainage 38m

Ch. 38m (Image 10)

Image 10 reveals cracks forming in the joint tie-in and the use of different aggregates is causing weakness in the surface layer. Road marking are in reasonable condition.



Image 10 – Chainage 38m

Ch. 40m (Image 11)

Image 11 reveals fretting (aggregate loss from the surface layer) along the crown line of the carriageway.



Image 11 – Chainage 40m

Ch. 57m (Image 12)

Image 12 reveals the failure of manhole surround, which is usually the symptom of partial or total failure of the road surface layer. In addition, road markings are in poor condition.



Image 12 – Chainage 50m

Ch. 62m (Image 13)

Image 13 reveals settlement of a patch repair. Generally road markings are in reasonable condition and kerbs are in poor condition.



Image 13 – Chainage 62m

Ch. 82m (Image 14)

Image 14 reveals fretting of the surface course, which is usually caused by the loss of aggregate in the road surface. Due to water ingress this will eventually cause potholes.



Image 14 – Chainage 82m

Ch. 104m (Image 15)

Image 15 reveals the failure of the gully surround and patch repair. This failure does not require immediate repair, however, it may be likely that these two patch repairs will form potholes. In addition, road markings are in poor condition.



Image 15 – Chainage 104m

Ch. 107m (Image 16)

Image 16 reveals the failure of the gully surround and patch repair. This failure does not require immediate repair, however, it is considered that these two patch repairs will form potholes.



Image 16 – Chainage 107m

Ch. 125m (Image 17)

Image 17 reveals crazing of the surface course, which is usually the symptom of partial or total failure of the road surface layer.

In addition, potholes are forming along the joint. Not all potholes that form on roads require immediate repair and most reported to us generally receive a lower category of priority for repair depending on their depth, position in the road and the volume of traffic using the route. In addition, road markings are in poor condition.



Image 17 – Chainage 125m

Ch. 172m (Image 18)

Image 18 reveals a pothole, cracking and crazing forming around the ironwork. Road markings and kerbs generally in poor condition.



Image 18 – Chainage 172m

Ch. 176m (Image 19)

Image 19 reveals the failure of several patch repairs. This failure does not require immediate repair, however, it is considered that these patch repairs are likely to form potholes. In addition, road markings are in poor condition.



Image 19 – Chainage 176m

Ch. 192m (Image 20)

Image 20 reveals reveals the failure of several patch repairs surrounding ironwork. This failure does not require immediate repair, however, it is considered that these patch repairs are likely to form potholes. In addition, road markings are in poor condition.



Image 20 – Chainage 192m

Ch. 192m (Image 21)

Image 21 reveals the failure of several patch repairs forming cracking, crazing and potholes. This failure does not require an immediate repair, however, it is considered that these road surface failures will be exacerbated by water ingress and freeze thaw effects. In addition, road markings are in poor condition.



Image 21 – Chainage 192m

Ch. 192m (Image 22)

Image 22 reveals the failure of several patch repairs forming cracking and crazing. This failure does not require immediate repair, however, it is considered that these road surface failures will be exacerbated by water ingress and freeze thaw effects. In addition, road markings are in poor condition.



Image 22 – Chainage 192m

Ch. 192m (Image 23)

Image 23 reveals the current condition of traffic bollards that are in reasonable condition. However road markings are in poor condition and kerbs are in reasonable condition.



Image 23 – Chainage 192m

Ch. 192m (Image 24)

Image 24 reveals the failure of several patch repair forming cracking, crazing and potholes. This failure does not require immediate repair, however, it is considered that these road surface failures will be exacerbated by water ingress and freeze thaw effects. In addition, road markings are in poor condition.



Image 24 – Chainage 192m

Ch. 192m (Image 25)

Image 25 reveals the failure of several patch repair forming cracking, crazing and potholes. This failure does not require immediate repair, however, it is considered that these road surface failures will be exacerbated by water ingress and freeze thaw effects. In addition, road markings are in poor condition.



Image 25 – Chainage 192m

3.0 Conclusion

The road is in generally poor condition and defects have formed on the road surface including shallow potholes, surface deterioration, edge failure, cracking and crazing. In addition, kerbs and road markings are in poor condition.

A further report will be submitted following the completion of the proposed residential development shown on the site plan contained in Appendix A.

4.0 Appendices

- Appendix A – Proposed Site Plan
- Appendix B – BDi Drawing Number 22131.006A – Photograph Location Plan.
- Appendix C – Topographical Survey
- Appendix D – Road Survey Extents

APPENDIX A

PROPOSED LAYOUT AT 1:250
ROUGH BIRCHWORTH LODGE,
ROUGH BIRCHWORTH LANE,
OXSPRING



1) This drawing and the design and details depicted thereon are the copyright of Peter Dimberline Chartered Architect.
 2) All dimensions on this drawing are to be checked by the Contractor and any discrepancies are to be reported to the Architect.
 3) Do not scale critical dimensions off this drawing.
 4) Contractor to ensure that all Health & Safety requirements (CDM Regulations) in relation to this project will be complied with.






This group of trees within the site curtilage are to be retained and root protection areas are shown in brown. Trees designated T1, T3, T47, T46, T43, T37, T36, T35 and T33. If plot 14 extends marginally into the root protection area, this may require none-intrusive foundations, for example mini-pile type.

Proposed habitat zone within this general area.

- A total of 22 dwellings proposed as listed below.
- phase 1 affordable dwellings 7no. (A mix of 3 and 2 bed)
 - phase 1 dwellings 7no. (Generally 4 bed)
 - phase 2 dwellings 7no. (Generally 4 bed)
 - 'signature plot' 1no. (Min 4 bed)
- NB:

All dwellings comply with minimum rear garden space as set out in the SYRDG ie a min 50 sq m for 2 bed houses and 60 sq m for 3 bed and over

Indicative new tree planting thus :



REVISIONS
 'B' Layout amended to include final highway requirements
 'A' Layout amended in accordance with planning request

PETER DIMBERLINE Dip Arch, RIBA
CHARTERED ARCHITECT

2 TIPSEY COURT, STAINCROSS
 BARNSELY, S75 6FZ

tel/fax (01226) 390947
 email: pdimberline@tiscali.co.uk

CLIENT	Mr P Faxon
PROJECT	Proposed residential development
LOCATION	Site off Roughbirchworth Lane, Oxspring, (South of Trans Pennine Trail)
DRAWING	Proposed site layout
SCALES	1:250
DATE	Oct '18
DRWG No.	2017/28/03
REV.	B
DRAWN BY	PD

APPENDIX B



This drawing is to be read in conjunction with all other relevant documentation.
Do not Scale
 All setting out by contractor. Report all discrepancies to bdi Structural Solutions.
Drawing Copyright of BDI Structural Solutions ©
 Client required to comply with requirements of Party Wall Act as required by nature of work.

NOTES

1. THIS DRAWING IS TO BE READ IN CONJUNCTION WITH THE SPECIFICATION AND ALL RELEVANT ENGINEERS, ARCHITECTS AND SUBCONTRACTORS DRAWINGS.
2. DO NOT SCALE FROM THIS DRAWING, USE ONLY FIGURED DIMENSIONS AND IF IN DOUBT ASK. ALL DIMENSIONS ARE IN METRES.
3. LAYOUT TO BE USED FOR ROAD CONDITION PHOTOGRAPH LOCATIONS ONLY.

LEGEND

PLANNING

Rev	Date	Description	Drawn	Chkd	Rev'd
A	23.10.23	GENERAL AMENDMENTS	AJ	JJ	JJ
0	02.12.22	FIRST ISSUE, FOR APPROVAL	AJ	JJ	JJ

bdi Structural Engineering Solutions
 Stafford Court, Washway Road, Sale, M33 7PE
 www.bdistructural.com
 T: 0161 969 3886 F: 0161 969 3884 E: info@bdistructural.com

Client: Mr P Faxon

Project: Proposed Residential Development Roughbichworth Lane, Oxspring (South of Trans Pennine Trail)

Drawing Title: Road Condition Report Photograph Locations - Sheet 1 of 2

Scale	1:200 at A1	Dwg No.	22131-006
Drawn	AJ	Checked	JJ
Reviewed	JJ	Reviewed	JJ
Originated Date	02.12.2022	Status/Rev	A



Oxspring
Primary
School



Image 23 (Chainage 188m)



Image 21 (Chainage 192m)



Image 25 (Chainage 192m)

402100.000N

This drawing is to be read in conjunction with all other relevant documentation.
Do not Scale
All setting out by contractor. Report all discrepancies to bdi Structural Solutions.
Drawing Copyright of BDI Structural Solutions ©
Client required to comply with requirements of Party Wall Act as required by nature of work.

NOTES

1. THIS DRAWING IS TO BE READ IN CONJUNCTION WITH THE SPECIFICATION AND ALL RELEVANT ENGINEERS, ARCHITECTS AND SUBCONTRACTORS DRAWINGS.
2. DO NOT SCALE FROM THIS DRAWING, USE ONLY FIGURED DIMENSIONS AND IF IN DOUBT ASK. ALL DIMENSIONS ARE IN METRES.
3. LAYOUT TO BE USED FOR ROAD CONDITION PHOTOGRAPH LOCATIONS ONLY.

LEGEND



Image 22 (Chainage 192m)



Image 16 (Chainage 107m)



Image 14 (Chainage 82m)



Image 18 (Chainage 172m)



Image 19 (Chainage 176m)



Image 17 (Chainage 125m)



Image 15 (Chainage 104m)



Image 13 (Chainage 62m)



PLANNING

Rev	Date	Drawn	Chkd	Rev'd
0	23.10.23	AJ	JJ	JJ

bdi
Structural Engineering Solutions
Stafford Court, Washway Road, Sale, M33 7PE
www.bdistructural.com
T: 0161 969 3886 F: 0161 969 3884 E: info@bdistructural.com

Client: Mr P Faxon

Project: Proposed Residential Development Roughbirchworth Lane, Oxspring (South of Trans Pennine Trail)

Drawing Title: Road Condition Report Photograph Locations - Sheet 2 of 2

Scale: 1:200 at A1	Drg No. 22131-007
Drawn: AJ	Checked: JJ
Reviewed: JJ	Originated Date: 02.12.2022
Status/Rev: 0	




Image 25 (Chainage 192m)



Image 23 (Chainage 188m)



Image 21 (Chainage 192m)

402100.000N



Image 20 (Chainage 192m)



Image 22 (Chainage 192m)



Image 16 (Chainage 107m)



Image 24 (Chainage 192m)



Image 18 (Chainage 172m)



Image 19 (Chainage 176m)



Image 17 (Chainage 125m)



Image 104m

This drawing is to be read in conjunction with all other relevant documentation.
Do not Scale
All setting out by contractor. Report all discrepancies to bdi Structural Solutions.
Drawing Copyright of BDI Structural Solutions ©
Client required to comply with requirements of Party Wall Act as required by nature of work.

NOTES

1. THIS DRAWING IS TO BE READ IN CONJUNCTION WITH THE SPECIFICATION AND ALL RELEVANT ENGINEERS, ARCHITECTS AND SUBCONTRACTORS DRAWINGS.
2. DO NOT SCALE FROM THIS DRAWING. USE ONLY FIGURED DIMENSIONS AND IF IN DOUBT ASK. ALL DIMENSIONS ARE IN METRES.
3. LAYOUT TO BE USED FOR ROAD CONDITION PHOTOGRAPH LOCATIONS ONLY.

LEGEND

PLANNING

Rev	Date	Drawn	Chkd	Rev'd
0	23.10.23	AJ	AJ	JJ

bdi Structural Engineering Solutions
 Stafford Court, Washway Road, Sale, M33 7PE
 www.bdistructural.com
 T: 0161 969 3886 F: 0161 969 3884 E: info@bdistructural.com

Client: Mr P Faxon

Project: Proposed Residential Development Roughbichworth Lane, Oxspring (South of Trans Pennine Trail)

Drawing Title: Road Condition Report Photograph Locations - Sheet 2 of 2


Scale: 1:200 at A1 Drg No. 22131-008

Drawn	Checked	Reviewed
AJ	JJ	JJ

Originated Date: 02.12.2022 Status/Rev: 0

APPENDIX C

1) This drawing and the design and details depicted thereon are the copyright of Peter Dimberline Chartered Architect.
 2) All dimensions on this drawing are to be checked by the Contractor and any discrepancies are to be reported to the Architect.
 3) Do not scale critical dimensions off this drawing.
 4) Contractor to ensure that all Health & Safety requirements (CDD Regulations) in relation to this project will be complied with.



Existing topographical site plan at 1:250

REVISIONS PETER DIMBERLINE Dip Arch, RIBA CHARTERED ARCHITECT 2 TIPSEY COURT, STAINCROSS BARNSELY, S75 6FZ tel/fax (01226) 390947 email: pdimberline@tiscali.co.uk	
CLIENT Mr P Faxon	
PROJECT Proposed residential development	
LOCATION Site off Roughbichworth Lane, Oxspring, (South of Trans Pennine Trail)	
DRAWING Existing topographical site layout	
SCALES 1:250	DATE Oct '18
DRWG No. 2017/28/01	DRAWN BY PD
REV.	

APPENDIX D

Limits of Condition Survey

