



Notes:

Existing garage utilises a steel frame, steel corrugated panels and timber barn doors.

The Garage is in a state of disrepair with the steel frame twisted, roofing panels broken/missing and timber doors unable to be opened.

Existing Detached Garage

**91 Pye Avenue, Mapplewell,
S75 6AG**

1:100 @ A4

**All Dimensions in
Millimeters unless stated
otherwise**

**Drawings By Edward
Barnbrook**