

BEFORE YOU EXCAVATE - If in doubt as to the position of our plant, please call our External Works Control -
Telephone: (01482) 603466.

REMEMBER - If you damage the Company plant you will be liable to pay the cost of carrying out a repair.

There may be OPTICAL FIBRE CABLES in the vicinity of your works. Great care must be taken to avoid damage as these cables are very expensive to repair. Also, laser light travels along the fibres and the precautions outlined in BS 4803 Part 3 should be adhered to.



FOR ADVICE call our External Works Control Telephone: (01482) 603466

KEY		
PLANT	PROPOSED	EXISTING
UNDERGROUND DUCT	---	---
JOINING CHAMBER	■	■
MANHOLE	■	■
BURIED BOX	■	■
CABLE DIRECT IN THE GROUND	ND or DIG	ND or DIG
POLE STAY	○	○
COUPLING TEE	×	×
REDUCER	△	△
CABINET	■	■
JOINING POST	○	○
AERIAL CABLE	---	---
CABLE ON WALL	---	---
DISTRIBUTION JOINT IN CHAMBER	■	■
INTERNAL & EXTERNAL TERMINAL BLOCK	■	■
KIOSK	■	■

CONTRACTOR PROPOSALS SHOWN BLUE

THE POSITIONS OF THE COMPANY'S PLANT ARE SHOWN AS ACCURATELY AS POSSIBLE BUT THE POSITIONS MUST BE REGARDED AS APPROXIMATE ONLY

BSAN 002
BARNSELY

VALID UNTIL/...../.....

Based upon Ordnance Survey digital maps with the permission of The Controller of Her Majesty's Stationery Office, (c) Crown copyright licence ALD50363A

Scale 1:500

08/08/2009

