

Method Statement

Allwayste Recycling

Unit 1-3 Shawfield Road
Carlton Ind Est
Carlton
Barnsley
S71 3HS

Approved by: Tim O'Donnell

Prepared by: Dave Riley

Approver's name: Tim O'Donnell

Title: Inert Crushing.

Approvers Title: Site Manager

This document is deemed to be an official Safety Document and all affected personnel must sign to acknowledge induction on its contents. It is the responsibility of the "Nominated Manager" to ensure that the induction is undertaken before allowing the task to commence.

Purpose

To ensure all personnel connected to the task at Allwayste Recycling are inducted into the method as detailed below.

Responsibilities

It is the responsibility of the line manager to ensure that all personnel are inducted, and understand, this procedure. It is the responsibility of the individual to carry out his/her tasks, as described in this document.

Training

Nominated Managers are responsible for ensuring that relevant personnel are suitably trained to carry out this procedure.

This induction should be used as part of the individuals "Training Programme"

P.P.E Requirements



1. Method

- 1.1 The purpose of this is to reduce inert material by means of crushing with a crusher bucket into the waste stock piles on the area within the permitted site.
- 1.1 Site operatives will be given strict instructions to operate the crusher at no more than 2 metres high to prevent dust becoming airborne and escaping from site, no crushing to be carried out in adverse weather conditions I.E windy days. Dust suppression water must be used when crushing activities are in use
- 1.3 Plant machinery will be used on top of the stock piles to crush the material at a lower level and at no point will plant machinery be allowed to crush at a height above 2 meters.
- 1.4 All waste will be stored into graded piles to ready for removal from site.

2.

- 2.1 The plant machinery operator will proceed to the area and safely crush the material into the waste stock piles in the specific designated area. All Site Rules must be complied with and PPE worn at all times. Only work in areas specified by the site manager.
- 2.2 On completion of the task the plant machinery operative must report back to the site manager before leaving the operation area.

**ALL ACCIDENTS AND DANGEROUS ACTIVITIES MUST BE REPORTED TO THE SITE
MANAGER IMMEDIATELY.**

