

APPENDIX 2 – PHOTOGRAPHS




Photograph number 1 showing the farmland prior to the erection of an agricultural building in 2016. The fields in the holding are under cultivation as can be seen from the darker green areas.



Photograph number 2 showing the agricultural building erected and the yard and living accommodation area being prepared. Note the fields to the east which are within the agricultural holding which have been cut and baled for haylage.



Photograph number 3 showing the farm in 2018 where the hay has been cut on the west side field and on the southeast of the holding either side of the stream.



Photograph number 4 showing the agricultural building, the riding yard, turnout pen and the living accommodation in March 2022. Note the area south of the turnout pen circle for storing manure.



Photograph number 5 showing the rare breed sheep kept at the farm.



Photograph number 6 showing the rare breed sheep at the trough and lick.



Photograph number 7 showing the excavation depth for the tiered area to the rear of the slab for the house and the paved area construction in support of gabion wall so the excavation is benched and then sealed by the paving to avoid water ingress into the stratum.



Photograph number 8 showing the upper gabion wall founded on the concrete strip footing and slab then paved to prevent water ingress into the mudstone beneath. The paved area is covering the gabion wall to support the excavation in mudstone for the house and provides a lateral force on the upper gabion wall foundation. The small wooden structure is a tack room and office for the business and is hidden from view in the landscape. The paved area and tack room are used for visiting guests to the livery stable and rare breeds farm.



Photograph number 9 showing part of main shed containing hay and bedding straw for lambing ewes. The shed is used to keep fodder, implements, sheep and horses in foal sheltered from the colder wet weather.



Photograph number 10 showing main shed blending into landscape with no visible signs of the house, paved area or the small tack room and office when looking from the access road to the south.

