

# High Street/ Crabtree Drive, Great Houghton – Dilapidation Survey

Carried out 03.12.2025

**1** – Entrance to bus stop off High Street onto Crabtree drive.



**2** – Patches of reinstated tarmac highway cracking and rutting.




**3** – Highway and Footpath in good condition.



**4** – Highway and Kerb line in good condition.



**5** – Carriageway generally in good condition.



**6** – Very Minor Cracking along centreline of highway.



**7** – HRW flags leaning onto Footpath.



**8** – Gully lids to receive heavy traffic, in fairly good condition.



**9** – Further photo of gully, crack in tarmac to the side of lid.



**10** – Carriageway in good condition.



**11** – Gully blocked, needs to be cleared from debris.



**12** – Kerb line at bus stop in good condition, minor chipping.



**13** – Existing Joint in tarmac, minor cracking.



**14** – Chipping to kerbs at vehicle crossing.



**15** – Minor damage to kerbs at drop crossing from the south.



**16** – White lining has deterioration, to receive heavy traffic.



**17** – Manhole lid in wheel line, in poor condition lid rocking.



**18** – Drop crossing to North in good condition.

