







SECTION THROUGH TRIAL PIT
ON
EAST ELEVATION OF TRACTOR SHED

A1.4 – Tractor Shed and Annex Photographs




Photograph 49 – View of East Elevation




Photograph 50 – View of East Elevation showing trees



Photograph 51 – View of trial pit on East Elevation



Photograph 52 – View of West Elevation




Photograph 53 – View of rot to top of timber beam



Photograph 54 – View of timber beam tom West Elevation



Photograph 55 – View of structure adjacent to the Tractor Shed



Photograph 56 – View of South Elevation



Photograph 57 – View of North Elevation




Photograph 58 – View of Roof




Photograph 59 – View of failed purlin




Photograph 60 – View Internal wall construction




Photograph 61 – View of timber support beam and floor joists




Photograph 62 – View of first floor construction




Photograph 63 – View of Annex East Elevation




Photograph 64 – View of Annex West Elevation



Photograph 65 – View of Annex North Elevation



Photograph 66 – View of Annex North Elevation



Photograph 67 – View of Annex South Elevation



Photograph 68 – View of Annex Roof



Photograph 69 – View of crack to window in North Elevation