






Gouge in footway tarmac.



Chipped kerb on splitter island.



Cracked kerb on perimeter footway.



Existing road markings are in the process of being burnt off and repainted, extent of these works is unknown.

Date of Survey: 27.11.2018

Notes:
Extent of survey agreed on site with BMBC engineer.

During the survey, line painters arrived at site to modify the existing road markings. The full extent of these works is unknown.

The roundabout and exits have been constructed recently and are generally in good condition.

E&P Comments
29.11.18



39724/04/AP/JEST
Rockingham, Hoyland
Road Condition Survey