

Unit 13 NOT PART OF APPLICATION

This old stone building has had the internal floors removed about 25 years ago. The building appears stable although it has had a steel cradle built around the outside to aid that stability which was severely jeopardised when the first floor was removed. Internally the building is lined in brickwork.

A large hole has been crudely blasted through the east wall to give access for farm produce-bales etc. there are occasional holes in the walls some quite large.

Despite the steel cradle the south gable has moved out at the eaves; around 150mm in the south west corner, and 50mm in the south east corner. The dual pitched roof is of stone supported on 2 No. internal King Post Trusses and the north and south gable walls. The west wall is somewhat weathered.

Although the building appears sound, we could envisage some re-building of the south gable above 1st floor level at least. The weathered west wall could be addressed on a piecemeal basis. The holes could easily be repaired/re-instated and the installation of a 1st floor would be of great benefit to the structure for the long term. The roof appears reasonably sound. We feel re-development of this building as a domestic residence is quite possible.

We have not inspected foundations or timbers or those areas inaccessible or hidden and cannot comment on those areas but as a general strategy we believe the proposed development is feasible from a structural viewpoint.

Yours faithfully



T. Stower

For and on behalf of
Tim Stower & Partners Ltd