

KEY

— B6273 High St: Photos 1-28

- - - Crabtree Avenue Photos 1-18.



Access to bustop, tarmac in poor condition (11).

Cracking and depression in highway (3).

Manhole lid in wheel line, in poor condition lid rocking (10).

Area of ponding along kerbline (9).

Patchwork tarmac and crocodile cracking within highway (12).

Manhole cover in poor condition to receive heavy traffic (16).

Area of patchwork tarmac, rutting and cracking present (18).

Patchwork tarmac cracking and rutting (19).

Cracking in carriageway in junction entrance to park lane (20).

Manhole which will receive heavy traffic have sunk and cracked (21).

Area of cracking and rutting when turning into village on the bend (22).

Cracking and pothole to be subject to heavy traffic (24).

Crabtree Avenue:

White lining has deterioration, to receive heavy traffic(16).

Chipping to kerbs at vehicle crossing(14).

Existing Joint in tarmac, minor cracking(13).

Gully Blocked, needs to be cleared from debris(11).

Kerb line at bus stop in good condition, minor chipping(12).

Further photo of gully, crack in tarmac to side of lid(9).

Manhole lid in wheel line, in poor condition lid rocking(17).

Minor damage to kerbs at drop crossing from the south(15).

HRW flags leaning onto footpath(7).

Very minor cracking along centerline of highway (6).

Patches of reinstated tarmac highway cracking and rutting (2).