



PHOTOGRAPH 1

THE EXISTING SURVEYED GROUND, WITHIN THE CURTILAGE SHOWING THE WOODEN PLANK AND VISQUEEN RETAINING THE LOOSE SOIL, PRIOR TO THE CONSTRUCTION OF THE EXTERNAL WALL OF THE BUILDING.



PHOTOGRAPH 2

THE EXISTING SURVEYED GROUND, WITHIN THE CURTILAGE, SHOWING THE WOODEN PLANK AND VISQUEEN RETAINING THE LOOSE SOIL, PRIOR TO THE CONSTRUCTION OF THE EXTERNAL WALL OF THE BUILDING.



PHOTOGRAPH 3


THE EXISTING SURVEYED GROUND, WITHIN THE CURTILAGE, SHOWING THE WOODEN PLANK AND VISQUEEN RETAINING THE LOOSE SOIL, PRIOR TO THE CONSTRUCTION OF THE EXTERNAL WALL OF THE BUILDING.



PHOTOGRAPH 4

THE EXISTING GROUND, WITHIN THE CUTILAGE, ADJACENT TO THE EXTERNAL WALL OF THE BUILDING, FOLLOWING WEEDING & PREPARATION FOR SPRING PLANTING. THIS WAS OBSERVED BY MR PAUL DOHERTY AND MR ROBERT TOLLYFIELD ON THEIR SITE VISIT OF 12/3/21, TOGETHER WITH THREE WITNESSES WHO WERE IN ATTENDANCE AT THAT TIME. THIS EXISTING GROUND HAS ALSO BEEN OBSERVED BY SIR STEPHEN HOUGHTON ON HIS SITE VISIT OF 8/4/21.

Photograph 5



PHOTOGRAPH 5

THE EXISTING GROUND, WITHIN THE CURTILAGE, ADJACENT TO THE EXTERNAL WALL OF THE BUILDING, FOLLOWING WEEDING AND PREPARATION FOR SPRING PLANTING. THIS WAS OBSERVED BY MR PAUL DOHERTY AND MR ROBERT TOLLYFIELD ON THEIR SITE VISIT OF 12/3/21 TOGETHER WITH THREE WITNESSES WHO WERE IN ATTENDANCE AT THAT TIME. THIS EXISTING GROUND HAS ALSO BEEN OBSERVED BY SIR STEPHEN HOUGHTON ON HIS SITE VISIT OF 8/4/21



PHOTOGRAPH 6

TAKEN BY MR PAUL DOHERTY (ENFORCEMENT OFFICER LPA) IN MARCH 2019. SHOWING UNDISTURBED LAND WITHIN THE CURTILAGE ADJACENT TO THE PROPOSED BUILDING. THIS IS THE AREA OF LAND THAT MR ANDREW BURTON (LPA PLANNING OFFICER) HAS REQUESTED TO SEE(ref e/mail 5/6/2020 15.28 to Mr Robert Agus.). THIS IS THE SAME AREA OF LAND, AS SHOWN IN PHOTO NUMBER TWO, PRIOR TO IT BEING WEEDED AND SURVEYED IN DECEMBER 2020. THE SHRUB AND WHITE PAINTED FENCE PANEL CAN BE SEEN CLEARLY ON BOTH PHOTOS.



PHOTOGRAPH 7

TAKEN BY MR PAUL DOHERTY (LPA ENFORCEMENT OFFICER) IN MARCH 2019, SHOWING UNEXCAVATED LAND, WITHIN THE CURTILAGE, ADJACENT TO THE PROPOSED BUILDING. THIS IS THE AREA OF LAND THAT MR ANDREW BURTON (LPA PLANNING OFFICER HAS REQUESTED TO SEE (ref. e/mail 5/6/2020 15.28 to Mr Robert Agus.) THIS IS THE SAME AREA OF LAND, AS SHOWN IN PHOTO NUMBER THREE, PRIOR TO IT BEING WEEDED AND SURVEYED IN DECEMBER 2020. THE PLASTIC BLACK BIN CAN BE SEEN ON BOTH PHOTOS.



PHOTOGRAPH 8
MR ROBERT TOLLYFIELD PLANNING OFFICER, ON HIS SITE VISIT ON 12/3/21, EXAMINING THE
EXISTING GROUND, WITHIN THE CURTILAGE, ADJACENT TO THE EXTERNAL WALL OF THE BUILDING.



PHOTOGRAPH 9

SHOWING WORK ON GOING TO THE EXTERNAL WALL OF THE BUILDING, ADJACENT TO THE EXISTING LAND, WITHIN THE CURTILAGE, WITH NO GAP. THE SHRUB AND WHITE PAINTED FENCE PANEL THAT APPEARS IN MANY OF THE PHOTOS CAN CLEARLY BE SEEN.



PHOTOGRAPH 10
SHOWS THE ONGOING WORKS TO THE EXTERNAL WALL OF THE BUILDING, ADJACENT TO THE
EXISTING LAND, WITHIN THE CURTILAGE, WITH NO GAP. THE BLACK BIN THAT APPEARS IN MANY OF
THE PHOTOS CAN CLEARLY BE SEEN.