Ref 9114431

Insured Mrs Davidson

Date 21/9/2022

Time

Meeting with









Built off a concrete slab. This garage was added on to the side of the house a year or two after construction.





Ref _____

Insured _____

Date _____

Time _____

Meeting with _____



Rear steel lintel pulled out with very limited bearing remaining.







Circa 15mm on 940mm level on brick courses on the rear garage wall towards the rear RH corner.



Infill cut bricks to rear above the door.



Rear Elevation

Ref _____

Insured _____

Date _____

Time _____

Meeting with _____



Ref _____

Insured _____

Date _____

Time _____

Meeting with _____



18mm drop over 940 level.

Ref _____

Insured _____

Date _____

Time _____

Meeting with _____



Bricks rotating outwards on the catnic over the front door.





Plumb to front corner.



Circa 15mm on 940 level leaning outwards to rear RH corner. Circa 3m to eaves and circa 4500 to ridge.





Ref _____

Insured _____

Date _____

Time _____

Meeting with _____



Garage Slab has pulled away from the House - Rear LH corner of Garage