Design and Access Statement – HSBC Penistone St Mary's Street
Document date 13.04.2015
Rev

Site Address:
HSBC Bank plc
4 St Mary's Street
Penistone
S36 6DT



1. **Introduction:**

As part of HSBC's ongoing refurbishment programme it is proposed to replace the External ATM's at this site because they have reached the end of their service life.

2. **Property Description:**

Bank, shop and offices. Late C19. Coursed squared rubble with ashlar dressings. Westmorland slate roof. Two storeys and attic. An ordered but asymmetrical curving facade of 10 bays on a corner site. All door and window openings are elliptical-arched. The central 3 bays, on the corner, are symmetrical with a central door with moulded surround. To each side is a large shop window with elaborate spandrel treatment and joggled lintel. The left 4 bays have a doorway to each side, that to left more elaborate with pilaster jambs, pulvinated frieze and triangular pediment. Between the doors are 2 windows, as before but smaller and plainer. The 3 bays to right are simpler with a 3-light window with elliptical-headed lights, and 2 doorways. Two moulded cornices between floors. 1st-floor windows are of two and three lights as before, and a single central light. The left 2 bays are surmounted by a shaped gable with an ashlar stack at apex. The right 2 bays are surmounted by a plainer gable with finial. Curved roof. Three gabled dormers. Several stone stacks with ashlar strings and cornices. An important corner site.

http://list.historicengland.org.uk/resultsingle.aspx?uid=1286793&searchtype=mapsearch

3. **Proposals**

The existing external ATM's are coming to the end of their service life and are due for replacement. These will be replaced with the new models providing the same services. It is proposed to replace the existing external ATM's to enable more adequate access for disabled users. The Existing external ATM's are currently situated through the stonework located on the front elevation. It is proposed to install two of the new machines 'Like for Like' through new apertures, one of which to be equality act compliant. Apertures may need slight adjustment to suit the new machines. Wall and finishes made good to match existing.

