

SLIDE 1

ADJACENT LAND



INTERNAL
INTERNAL

SLIDE 2


SYK 70447
1
SYK70447
SYK338481
SYK338481
Pond
Round Spring
Old Tin Shaft
WOOD MAIN ROAD

SLIDE 3

ADJACENT LAND











SLIDE 4

ADJACENT LAND













ADJACENT LAND



Looking West along Maple Road. Existing demarcation fence is 1000mm H, with 75mm X 75mm wooden posts, set (originally) at approximately 3000mm spacing.





General structure debilitation approximately 50m along. Original fence meshing is 150mm X 90mm galvanised wire, (encouraging foothold climb-over), with top-running tension wire (snipped for access in many places).



Broken fence post, unsupported mesh.



Area of ex-'mirror post', mesh support wires loose, etc.





Broken support post, (example of many).



Commonly used 'climb-over' point. Sagging, unsupported mesh.

ADJACENT LAND



Typical of broken posts and wires. Public trespass damage.



Routinely damaged fence area, to unofficial path across land.



Climb-over point damage. Reverse angle.



Further detached/rotted post example, with distorted meshing.



Fence needs re-alignment behind manhole.



Maple Road N/W Corner. Unsolicited signage!!



Maple Rd N/W corner. Broken posts, mesh scrunched up behind BT boxes.



N/W corner BT boxes. Open section, mesh absent/damaged (Proposed position of new lockable access/maintenance gate).

ADJACENT LAND










NW Corner fence has had many repairs, tension wires been ‘snipped’ and re-fastened in a multitude of places. West side bus shelter is common gathering, climbing and litter throwing area, (nearby Mc Donald’s).

South West corner approaching Public Right of Way; Many vandalised posts/downtrodden meshing sections, previous repairs.









S/W end of fence line: Causeway open to steep banking, (Recurrent vandalism)

Bottom and along official Public Footpath across wooded area, showing extensive structural damage, loss of HSBC fence line to LEFT, (**NOT** included on previous 252m replacement quotation). Petrol station boundary fence on the right.

ADJACENT LAND







General views through internal woodland, (**NOT** included on previously obtained replacement quotation), various areas of Public Footpath demarcation fence damage, both malicious and age related, rotted posts, etc. Concrete posts (on the right hand side) with **publicly accessible barbed wire** may be the responsibility of neighbouring properties/landowners?