Eastwood & Partners
CONSULTING ENGINEERS

PHASE 1 GEOTECHNICAL AND GEO-ENVIRONMENTAL SITE INVESTIGATION

NETHER MILL FARM, PENISTONE

FOR

CHRIS CARR ARCHITECTS

ISSUE 1



35223-001 **16 October 2012**

Eastwood & Partners, St Andrew's House, 23 Kingfield Road, Sheffield, S11 9AS
Tel: 0114 255 4554 Fax: 0114 255 4330 mail@eastwoodandpartners.com www.eastwoodandpartners.com

Eastwood & Partners
CONSULTING ENGINEERS

E&P

PHASE 1 GEOTECHNICAL AND GEO-ENVIRONMENTAL SITE INVESTIGATION

NETHER MILL FARM, PENISTONE

FOR

CHRIS CARR ARCHITECTS

ISSUE 1

Job No.	:	35223
Report Status	:	Issue 1
Document Date	:	16 October 2012
Approved	:	M J Yates

Also at: Pearson Court, 3 Kings Road, Fleet, GU51 3DL Tel: 01252 360 580 Fax: 01252 360581

Directors: **G M Seaman** BSc, CEng, FICE, FIStructE **S D Preston** BEng, CEng, FICE, FIStructE **N J Baines** BSc, CEng, MICE, MCIWEM
P Richardson BSc, CEng, MICE, MIStructE **J M Wood** BSc, CEng, MICE, FIStructE **M J Yates** BSc(Eng), ACGI, CEng, MICE, FIStructE
S R Ellis, BEng, CEng, MIStructE, AMICE **K R Pursall** BEng, CEng, MIStructE
Senior Associates: **K Newsome** BSc, CEng, MICE, MIStructE **S J Mitchell** BSc, MSc, CEng, MEI, MCIBSE, MASHRAE
Associates: **A Jones** BEng, CEng, MICE, MIStructE **M Young** MA, CEng, MICE, MIStructE **C A Wood** BSc, CEng, MIStructE, AMICE
A ALLISON B.ENG **C A TOPLISS** BSC, CENV, CSCI, CGEOL, SILC, AMICE, FGS
S J English BEng, CEng, MIStructE **A R Priest** B.Eng

Eastwood & Partners (Consulting Engineers) Limited Registered No 1835021

CONTENTS

EXECUTIVE SUMMARY **5**
1.0 INTRODUCTION **7**
1.1 Terms of Reference 7
1.2 Context 7
1.3 Aims and Objectives 7
1.4 Scope of Investigation 7
2.0 THE SITE **9**
2.1 Description 9
2.2 History 12
2.2.1 The Site 12
2.2.2 The Surrounding Area 13
2.3 Geology 14
2.4 Hydrogeology 14
2.4.1 Groundwater Vulnerability 14
2.5 Hydrology 14
2.6 Mining 15
2.6.1 Coal Mining 15
2.6.2 Quarrying 16
2.7 Ground Gas 16
2.7.1 Landfill Gas 16
2.7.2 Radon Gas 17
2.8 Flooding 17
3.0 EXPECTED GROUND CONDITIONS **18**
4.0 GEOTECHNICAL APPRAISAL **19**
4.1 General 19
4.2 Foundations 19
4.3 Superstructure Precautions 19
4.4 Ground Slabs 19
4.5 Roadworks 20
4.6 Problems Due To Past Development 20
4.7 Excavation Problems 20
4.8 Surface Water Drainage 20
4.9 Sulphate Attack of Buried Concrete 20

5.0 CONTAMINATION APPRAISAL 21

5.1 Outline Conceptual Model 21

5.2 Possible Pollutant Linkages 22

6.0 RATIONALE FOR FURTHER INVESTIGATION 23

APPENDICES

Appendix 1 Site Features Plan, Drawing No. 35223/001A

Appendix 2 Envirocheck Report

Historical Ordnance Survey Maps

Coal Authority Mining Report