



**THURNSCOE
ROTHERHAM
HIGHWAY CONDITION SURVEY**

Commissioned By:	Andrew Bradley
On Behalf Of:	Keepmoat Homes
Local Authority:	Barnsley Metropolitan Borough Council
Inspection Date:	20 th September 2017
JLES Project Reference:	N/227/Thurnscoe/Cs

Prepared By:	
JLES Engineer	Mackenzie Gray
Approved By:	
JLES Divisional Director	Jamie Foster

Report Issued:	29 th September 2017
-----------------------	---------------------------------

This document has been prepared for the titled project (or named part thereof) and should not be relied upon or used for any other project without an independent check being carried out as to its suitability and prior written authorisation being obtained from JLES. JLES accepts no responsibility or liability for the consequences of the use of this document, wholly or in part, for any other purpose than that for which it was commissioned. Any persons so using or relying upon this document for such purpose do so at their own risk.

This report was prepared for the sole use of named Client, as defined above, and shall not be relied upon or transferred to any other party without express written authorisation of JLES. It may contain material subject to copyright or obtained subject to license; unauthorised copying of this report will be breach of copyright / license.

The findings and opinions provided in this document are given in good faith and are subject to the limitations imposed by employing site assessment methods and techniques, appropriate to the time of investigation and within the limitations and constraints defined within this document. The findings and opinions are relevant to the dates when the assessment was undertaken, but should not necessarily be relied upon to represent conditions at a substantially later date. In particular site deterioration and damage.

Further assessment, investigation, construction activities or passage of time may reveal conditions that were not found during the period of these investigations and therefore, could not have been taken into account in the preparation of the report. Where such information might impact upon stated opinions, JLES reserve the right to modify such opinions and costs expressed herein.

The findings and opinions conveyed, via this report are based on information obtained from a variety of sources as detailed in this report, and which JLES assumes to be reliable.

Where opinions expressed in this report are based on current available guidelines and legislation, no liability can be accepted by JLES for the effects of any future changes to such guidelines and legislation.


The limitations of liability of JLES for the contents of this document have been agreed with the Client, as set out in the terms and conditions of offer and related contract documentation.


CONTENTS

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	



REPORT CONTENTS

SECTION	DESCRIPTION
-	SITE PLAN <i>A drawing illustrating the proposed area which requires surveying.</i>
1	EXECUTIVE SUMMARY <i>Inspection notes & conclusions including a summary of the sites current status and all other considerations relevant to the condition of the highway.</i>
2	HIGHWAY CONDITION SURVEY <i>A full comprehensive photograph illustrated log of the comments & observations made by JLES during the highway inspection. This also includes a JLES remedial works rating.</i>
3	STREET LIGHTING CONDITION SURVEY <i>A full comprehensive photograph illustrated log of the comments & observations made by JLES during the highway inspection.</i>
4	APPENDICES <i>Schedule detailing key significant correspondences and documents sent, received or produced by JLES during compilation of report.</i>





SECTION	DESCRIPTION	
-	SITE PLAN	



- DESIGN CRITERIA - PRIVATE PLOTS
- Traditional Construction
 - Building Regulations Part A 2013, Part B1 2013, Part C 2013, Part D 2015, Part E 2015, Part F 2015, Part G 2016, Part H 2015, Part J 2013, Part L 2016, Part M 2016, Part P 2013
 - Code for Sustainable Homes Level 3 (November 2009 Technical Guidance) NOT APPLICABLE
 - Lifetime Homes (July 2010) NOT APPLICABLE
 - Design Quality Standards (Edition 2) NOT APPLICABLE
 - Housing Quality Indicators (HQI) NOT APPLICABLE
 - Secured By Design (section 2 part compliance) NOT APPLICABLE
 - Secured By Design (full accreditation) NOT APPLICABLE
 - Building for Life (12 point assessment) NOT APPLICABLE
 - English Partnerships Standards NOT APPLICABLE
 - Mobility Standards NOT APPLICABLE
 - Wheelchair Design Guide Standards NOT APPLICABLE
 - NHF Standards NOT APPLICABLE

- DESIGN CRITERIA - AFFORDABLE PLOTS
- Traditional Construction
 - Building Regulations Part A 2013, Part B1 2013, Part C 2013, Part D 2015, Part E 2015, Part F 2015, Part G 2016, Part H 2015, Part J 2013, Part L 2016, Part M 2016, Part P 2013
 - Code for Sustainable Homes Level 3 (November 2009 Technical Guidance) NOT APPLICABLE
 - Lifetime Homes (July 2010) NOT APPLICABLE
 - Design Quality Standards (Edition 2) NOT APPLICABLE
 - Housing Quality Indicators (HQI) NOT APPLICABLE
 - Secured By Design (section 2 part compliance) NOT APPLICABLE
 - Secured By Design (full accreditation) NOT APPLICABLE
 - Building for Life (12 point assessment) NOT APPLICABLE
 - English Partnerships Standards NOT APPLICABLE
 - Mobility Standards NOT APPLICABLE
 - Wheelchair Design Guide Standards NOT APPLICABLE
 - NHF Standards NOT APPLICABLE

J	MB	01.08.17	Knee rail replaced with railings fronting 56-60 & 66-68. Bin collection areas added. Small sections of railings (less than 900mm in length) removed. Railings omitted from plots 72,74,94,97,108. Fence relocated 65-68. Boundary treatment updated.
H	MB	24.07.17	Road 1 geometry changed to match existing. Plots 30-34 redesigned. Footpath added linking Road 1 and Road 4. Turning head added to Road 2. Parking for 100 & 107 amended.
G	MB	17.07.17	Layout updated to match Sketch Appraisal 8. Mix amended accordingly. Site redline added. Accommodation Schedule updated to show site areas and densities.
F	MB	29.06.17	Road 1 geometry changed to match existing. Plots 30-34 redesigned. Footpath added linking Road 1 and Road 4. Turning head added to Road 2. Parking for 100 & 107 amended.
E	MB	26.06.17	Layout updated to match Sketch Appraisal 8. Mix amended accordingly. Site redline added. Accommodation Schedule updated to show site areas and densities.
D	MB	13.06.17	Road 1 geometry changed to match existing. Plots 30-34 redesigned. Footpath added linking Road 1 and Road 4. Turning head added to Road 2. Parking for 100 & 107 amended.
C	MB	20.02.17	Layout updated to match Sketch Appraisal 8. Mix amended accordingly. Site redline added. Accommodation Schedule updated to show site areas and densities.
B	MB	12.10.16	Road 1 geometry changed to match existing. Plots 30-34 redesigned. Footpath added linking Road 1 and Road 4. Turning head added to Road 2. Parking for 100 & 107 amended.
A	MB	11.10.16	Layout updated to match Sketch Appraisal 8. Mix amended accordingly. Site redline added. Accommodation Schedule updated to show site areas and densities.

REVISION

DRAWING TITLE:
**PLANNING LAYOUT
PHASE 2**

PROJECT:
Residential Development

PROJECT ADDRESS:
School Street,
Thurnscoe

CLIENT:
KEEPMOAT HOMES

DRAWN	SCALE	DATE
MB	1:500 @ A1	23rd SEP. 2016
JOB NO.	DWG. NO.	REVISION
2238	02	J

queens tower lodge
77-79 east bank road
sheffield S2 3PX
T: 0114 2750263
M: 07443 596098
E: info.cga@btconnect.com
Company No. 9118738

Keepmoat, The Waterfront, Lakeside Boulevard,
Doncaster, DN4 5PL.
Tel: 01302 347605 www.keepmoat.com

© COPYRIGHT EXISTS ON THE DESIGNS AND INFORMATION SHOWN ON THIS DRAWING. • DO NOT SCALE FROM DRAWING ALL DIMENSIONS TO BE VERIFIED ON SITE PRIOR TO COMMENCING ANY WORK

PHASE 2 - APPRAISAL ACCOMMODATION SCHEDULE								
PRIVATE SALES UNITS			GIA		total GIA of type		No.	%
House Type			sq.ft.	sq.m.	sq.ft.	sq.m.		
621	Detached	2 bed. 3 person	621	57.7	8073	750.0	13	13
651	Semi-detached and terrace	2 bed. 4 person	651	60.5	18228	1693.4	28	29
857	Detached	3 bed. 5 person	857	79.6	5142	477.7	6	6
867	Detached	3 bed. 5 person	867	80.5	13872	1288.8	16	16
	Semi-detached	3 bed. 5 person	867	80.5	2601	241.6	3	3
955	Detached	3 bed. 6 person	955	88.7	16235	1508.3	17	18
1054	Semi-detached	3 bed. 5 person	1054	97.9	14756	1370.9	14	14
			SUB-TOTAL		78907	7330.7	97	100
AFFORDABLE UNITS			GIA		total GIA of type		No.	%
House Type			sq.ft.	sq.m.	sq.ft.	sq.m.		
740	Semi-detached	2 bed. 4 person	740	68.7	14800	1375.0	20	63
953	Semi-detached	3 bed. 5 person	953	88.5	11436	1062.4	12	38
			SUB-TOTAL		26236	2437.4	32	100
			TOTAL		105143	9768.1	129	

Unit Density:	14 Units/acre	Site Area (gross)	12.10	Acres	4.90
	34 Units/hectare	PCIS	1.95	Hectares	0.79
Area Density:	11143 sq.ft./acre	Undeveloped	0.72		0.29
	2557 sq.m./hectare	Site Area (net)	9.44		3.82

- GENERAL NOTES:
- This drawing is based on Haycock & Todd Topographical Survey, dated April 2013, job number 57847.
 - This drawing is to be read in conjunction with associated Boundary Treatment & Materials Drawings.
 - All contractors must visit the site and be responsible for taking and checking dimensions prior to undertaking of works.
 - Any discrepancies between drawings, specifications and site conditions must be brought to the attention of the Site Supervisor.
 - This drawing is for Planning purposes only. It is not intended to be used for construction purposes. Whilst all reasonable efforts are used to ensure drawings are accurate Chris Gothard Architectural accept no responsibility or liability for any reliance placed on, or use made of, this plan by anyone for purpose other than those stated above.

- Legend
- Existing dwelling
 - Private parking bay / drive
 - 1.8m high brick wall
 - 1.8m high close boarded timber screen fence
 - 1.5m high close boarded timber fence with 0.3m trellis above
 - 1.1m high steel railings
 - 0.6m high timber knee rail
 - front entrance door
 - secondary entrance
 - Lockable personnel gate
 - Visitor parking
 - 'Affordable' dwelling
 - Shared private driveway - Tarmacadam
 - Block paving to section of adoptable highway
 - 600mm margin to shared surface highway
 - Refer to Landscape Architects details
 - Existing tree as shown on Topographical Survey
 - Bin store
 - Bin collection point



SECTION	DESCRIPTION	
1	EXECUTIVE SUMMARY	

EXECUTIVE SUMMARY

1

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

THE INSPECTION


JLES ENGINEER:	Mackenzie Gray
LOCAL AUTHORITY:	
WEATHER CONDITIONS:	Dry
NOTES:	N/A

SUMMARY

JLES have undertaken an inspection of School Street. The footpaths throughout School Street are generally in a poor condition showing moderate signs of deterioration. There are a moderate number of damaged kerbs / pin kerbs, sunk kerbs / pin kerbs and the footway has numerous re-instatements that are beginning to show signs of failure.

The carriageway on School Street is in a reasonable condition, however, it is beginning to show signs of wear. It also appears to have been surface dressed.

The road markings at the entrance to School Street & various junctions throughout the carriageway are in a reasonable condition, however, they are beginning to show signs of wear / fading.




SECTION	DESCRIPTION	
2	HIGHWAY CONDITION SURVEY	

HIGHWAY CONDITION SURVEY						2
JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

FOOTPATH CONDITION SURVEY EXTENTS

Northern section of footpath survey leads North (see plan below).



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 1

LOCATION:	Northern section of footpath heading South, 0-50m.
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Re-instatements present within the footpath are showing signs of failure. C) Numerous damaged kerbs along the footpath.
NOTES:	N/A.
REMEDIAL WORKS RATING:	1 2 3 4 5 6 7 8 9▼ 10 LOWMEDIUMHIGH



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 2

LOCATION:	Northern section of footpath heading South, 50-100m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Re-instatements present within the footpath are showing signs of failure. C) Weed / vegetation growth encroaching onto the footpath. D) Numerous damaged kerbs along the footpath.									
NOTES:	Third party marking spray present within the footpath.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7	8	9▼	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 3

LOCATION:	Northern section of footpath heading South, 100-150m.									
OBSERVATION:	A) Footpath surface course appears to be in a good condition. B) 2No utility boxes present within the footpath, showing no defects.									
NOTES:	Third party marking spray present within the footpath.									
REMEDIAL WORKS RATING:	1	2	3▼	4	5	6	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 4

LOCATION:	Northern section of footpath heading South, 0-50m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear. B) Re-instatements present within the footpath appear to be in a good condition. C) 2No utility boxes present within the footpath, showing no defects. D) Numerous damaged kerbs along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 5

LOCATION:	Northern section of footpath heading South, 50-100m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear. B) Reinstatements present within the footpath appear to be in a good condition. C) 3Ne utility boxes present within the footpath, showing no defects. D) Weed growth present along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 6

LOCATION:	Northern section of footpath heading South, 100-136m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear. B) Re-instatements present within the footpath are showing signs of failure. C) Weed growth present along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 7

LOCATION:	Northern section of footpath heading South, 0-50m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Reinstatements present within the footpath are showing signs of failure. C) Weed growth present along the footpath. D) Numerous damaged kerbs along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 8

LOCATION:	Northern section of footpath heading South, 50-100m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Weed growth present along the footpath. C) Numerous damaged kerbs along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 9

LOCATION:	Northern section of footpath heading South, 0-50m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Weed growth present along the footpath. C) Numerous damaged kerbs along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7 ▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 10


LOCATION:	Northern section of footpath heading South, 50-78m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear. B) Numerous damaged kerbs along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5▼	6	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY						2
JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

FOOTPATH CONDITION SURVEY EXTENTS

Southern section of footpath survey leads South (see plan below).



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 11

LOCATION:	Southern section of footpath heading North, 0-25m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear. B) Numerous damaged kerbs along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 12

LOCATION:	Southern section of footpath heading North, 0-29m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Numerous damaged kerbs along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 13

LOCATION:	Southern section of footpath heading North, 0-37m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Weed / vegetation growth encroaching onto the footpath. C) Numerous damaged kerbs along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7 ▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 14

LOCATION:	Southern section of footpath heading North, 0-50m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Weed / vegetation growth encroaching onto the footpath. C) Re-instatement present along the footpath is showing signs of failure.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 15

LOCATION:	Southern section of footpath heading North, 50-83m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear. B) Re-instatements present within the footpath are showing signs of failure. C) Weed growth present along the footpath.									
NOTES:	N/A.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 16

LOCATION:	Southern section of footpath heading North, 0-65m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Re-instatements present within the footpath are showing signs of failure. C) Weed / vegetation growth encroaching onto the footpath. D) Numerous damaged kerbs along the footpath.									
NOTES:	Third party marking spray present within the footpath.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 17

LOCATION:	Southern section of footpath heading North, 0-50m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Re-instatements present within the footpath are showing signs of failure. C) Weed / vegetation growth encroaching onto the footpath.									
NOTES:	Third party marking spray present within the footpath.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 18

LOCATION:	Southern section of footpath heading North, 50-100m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Re-instatements present within the footpath are showing signs of failure. C) Weed / vegetation growth encroaching onto the footpath.									
NOTES:	Third party marking spray present within the footpath.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7 ▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 19

LOCATION:	Southern section of footpath heading North, 100-150m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Re-instatement present within the footpath is showing signs of failure. C) Weed growth present along the footpath.									
NOTES:	Third party marking spray present within the footpath.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 20

LOCATION:	Southern section of footpath heading North, 150-200m.									
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Re-instatement present within the footpath is showing signs of failure. C) Weed growth present along the footpath.									
NOTES:	Third party marking spray present within the footpath.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

ITEM 21


LOCATION:	Southern section of footpath heading North, 0-30m.										
OBSERVATION:	A) Footpath surface course is showing signs of wear / cracking. B) Weed growth present along the footpath.										
NOTES:	N/A.										
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7▼	8	9	10	
	LOW			MEDIUM				HIGH			
											



HIGHWAY CONDITION SURVEY						2
JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

CARRIAGEWAY CONDITION SURVEY EXTENTS

Northern section of carriageway survey leads North (see plan below).



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 22

LOCATION:	Northern section of footpath heading South, 0-50m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) 1N ₂ sunken gully present within the carriageway.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present. C) Third party marking spray present within the carriageway.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6	7▼	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 23

LOCATION:	Northern section of carriageway heading South, 50-100m.									
OBSERVATION:	Carriageway surface course is showing signs of wear.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 24

LOCATION:	Northern section of carriageway heading South, 100-150m.									
OBSERVATION:	Carriageway surface course is showing signs of wear.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present. C) Third party marking spray present within the carriageway.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 25

LOCATION:	Northern section of carriageway heading South, 150-200m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are beginning to wear / fade.									
NOTES:	Carriageway has been surface dressed.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6 ▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 26

LOCATION:	Northern section of carriageway heading South, 200-250m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are in a good condition.									
NOTES:	A) Carriageway has been surface dressed. B) Third party marking spray present within the carriageway.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

ITEM 27

LOCATION:	Northern section of carriageway heading South, 250-300m.										
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are in a good condition.										
NOTES:	Carriageway has been surface dressed.										
REMEDIAL WORKS RATING:	1	2	3	4	5▼	6	7	8	9	10	
	LOW			MEDIUM				HIGH			



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 28

LOCATION:	Northern section of carriageway heading South, 300-350m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are in a good condition.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 29

LOCATION:	Northern section of carriageway heading South, 350-400m.									
OBSERVATION:	Carriageway surface course is showing signs of wear.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 30

LOCATION:	Northern section of carriageway heading South, 400-450m.									
OBSERVATION:	Carriageway surface course is showing signs of wear.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 31


LOCATION:	Northern section of carriageway heading South, 450-490m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are beginning to wear / fade.									
NOTES:	Carriageway has been surface dressed.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY						2
JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

CARRIAGEWAY CONDITION SURVEY EXTENTS

Southern section of carriageway survey leads South (see plan below).



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 32

LOCATION:	Southern section of carriageway heading North, 0-50m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are beginning to wear / fade.									
NOTES:	Carriageway has been surface dressed.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 33

LOCATION:	Southern section of carriageway heading North, 50-100m.									
OBSERVATION:	Carriageway surface course is showing signs of wear.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 34

LOCATION:	Southern section of carriageway heading North, 100-150m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are in a good condition.									
NOTES:	Carriageway has been surface dressed.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 35

LOCATION:	Southern section of carriageway heading North, 150-200m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are beginning to wear / fade.									
NOTES:	Carriageway has been surface dressed.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 36

LOCATION:	Southern section of carriageway heading North, 200-250m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are beginning to wear / fade.									
NOTES:	Carriageway has been surface dressed.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 37

LOCATION:	Southern section of carriageway heading North, 250-300m.									
OBSERVATION:	Carriageway surface course is showing signs of failure.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6 ▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 38

LOCATION:	Southern section of carriageway heading North, 300-350m.									
OBSERVATION:	Carriageway surface course is showing signs of wear.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 39

LOCATION:	Southern section of carriageway heading North, 350-400m.									
OBSERVATION:	Carriageway surface course is showing signs of wear.									
NOTES:	A) Carriageway has been surface dressed. B) No road markings present.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		



HIGHWAY CONDITION SURVEY

2


JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



ITEM 40

LOCATION:	Southern section of carriageway heading North, 400-483m.									
OBSERVATION:	A) Carriageway surface course is showing signs of wear. B) Road markings are beginning to wear / fade.									
NOTES:	Carriageway has been surface dressed.									
REMEDIAL WORKS RATING:	1	2	3	4	5	6▼	7	8	9	10
	LOW			MEDIUM				HIGH		





SECTION	DESCRIPTION	
3	STREET LIGHTING CONDITION SURVEY	

STREET LIGHTING CONDITION SURVEY

3

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

STREET LIGHT	OBSERVATION	ASSOCIATED CONSIDERATIONS
LC1 	Ok.	N/A.
LC2 	Ok.	N/A.
LC3 	Ok.	N/A.

STREET LIGHTING CONDITION SURVEY

3

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

LC4



Ok.

N/A.

LC5



Ok.

N/A.

LC6



Ok.

N/A.

STREET LIGHTING CONDITION SURVEY

3

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



LC7



Ok.

N/A.

LC8



Ok.

N/A.

LC9



Ok.

N/A.

STREET LIGHTING CONDITION SURVEY

3

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



LC10



Ok.

N/A.

LC11



Ok.

N/A.

LC12



Ok.

N/A.

STREET LIGHTING CONDITION SURVEY

3

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs



LC13



Ok.

N/A.

LC14



Ok.

N/A.

LC15



Ok.

N/A.

STREET LIGHTING CONDITION SURVEY

3

JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

LC16

Ok.

The column appears to be day burning.




GENERAL STREET LIGHTING SUMMARY & NOTES

SUMMARY

Following a condition survey carried out by JLES the above street lighting and illuminated signage visual observations have been made.

APPENDICES						4
JLES Division:	Northern	Local Authority:	Barnsley Metropolitan Borough Council	Inspection Date:	20 th September 2017	
Project Name:	Thurnscoe	Location:	School Street, Thurnscoe	JLES Ref:	N/227/Thurnscoe/Cs	

APPENDICES			
SECTION	DESCRIPTION	DATE	FORM
A	Condition Survey Photographs	20 th September 2017	DVD
NOTE:	Refer to following sheets for copies of original documents		



SECTION	DESCRIPTION	
A	CONDITION SURVEY PHOTOGRAPHS	



JLES Northern
4100 Park Approach
Leeds
United Kingdom
LS15 8GB

northern@jlesgroup.com
0113 397 0420