

Photos of the exterior and interior taken on 29.12.2025

Exterior windows



Exterior: side elevation



Ties to provide structural stability



Ground floor front room



(Ceiling tiles)



Ground floor front room. Floor falling away due to subsidence



Ground floor front room. Floor falling away due to subsidence



Ground floor room



Internal door



Internal door



Internal door



Ground floor room (rear)

Floor falling away in corner due to subsidence, presumably from Ivy growth



Ground floor room (rear)

Floor falling away in corner due to subsidence, presumably from Ivy growth



Upper floor front room



Upper floor front room propped



Upper floor rear room (daylight noticeable from ceiling)



Upper floor front room stage

