

Extent of condition survey.

New patch of tarmac

Storage container was present here for site to the N-E. The road was observed to be generally quite dirty and whilst conducting the survey site personnel cars/lorries were observed parking on the pavement.

Marks and scratches to the pavement were observed throughout the survey area, see photo P08 as an example.

Several road markings were observed to be slightly faded, see example photo P20.

Site entrance

Date of Survey: 04.06.2021

Notes:

Extent of survey agreed on site with BMBC engineer.

We have included the more substantial defects as photo references, as denoted on the above plan. The full pack of survey photos will be included with submission, for reference.

A walkover along Sheffield road to the next roundabout and back along the Dearne Valley Parkway was also conducted, photos of this are included in the full survey pack.



E&P Comments
04.06.2021



39724/30/AP/SR
Rockingham, Hoyland
Road Condition Survey