Existing Ground Floor Layout



Existing roof layout

Notes

- Historic Oak Structure
- Modern timber repair/extension
- Steel structure
- Proposed Concrete Lintel designed by Structural Engineer
- New brickwork above ceiling level
- (11) Statement photo reference



To whole roof

New 50 x 150 timber rafters to replace modern rafters and to be fitted alongside historic rafters. Rafters are to span between wall plate and ridge purlin (new and historic).

New 50 x 150 rafers are NOT to be supported on intermediate purlins.

Proposed roof layout

Revision	Description	By	Date
B	Photograph references added. Rafter note added.	AVR	15/2/18
A	General amendments to proposed roof structure	AVR	12/2/18

CAD Info: G:\ACAD\ARCH

Essence Architecture Ltd.

Client
Mr and Mrs Campbell
Queen Anne's Lodge, Worsbrough Bridge

Project
Queen Anne's Lodge
Repair to Roof Structure

Drawing Title
Existing and Proposed Plans
Roof Structure

Scale	Status
A1 1:50	Listed Building

Drawn	Date
AVR	30/3/16

Project No.	Drawing No.	Revision
2013-05	LBC 01	B

Head Office: Upper Bagden House, Bagden Lane, Clayton West, Huddersfield, HD8 9LQ
Tel: 01484 865000
Fax: 01484 865071
Email: info@essencearchitecture.com
Web Site: www.essencearchitecture.com

ALL DIMENSIONS TO BE CHECKED ON SITE, DRAWING MUST NOT BE SCALED, TAKE FIGURED DIMENSIONS, THIS DRAWING IS THE PROPERTY OF ESSENCE ARCHITECTURE LTD. AND MAY NOT BE COPIED, USED, REPRODUCED OR DISCLOSED WITHOUT WRITTEN CONSENT