SITE INSPECTION SHEET

Site Name – 1909, Emerald Green, Penistone


Date – 28th April 2017

Inspected By – Mal Vickers

Notes – Visited site to meet with resident re overhanging tree being very close to his property, almost touching the gable end of his house and the roof.

The resident has a valid point and I have said we will look to do the work once the site has received its annual survey later this year and then tackle his issue and any issues the survey puts forward at the same time thus saving money on only one tree surgeons visit. As the tree is close but not touching the roof line yet he is happy with this suggestion.

Whilst on site I checked other properties adjacent to the woodland to see if there were any similar issues to deal with at the same time. Plan below shows the works required. Notes below explain and illustrate each area in turn.



A – Willow at the side of 34 Fullshaw Bank growing very close to property, suggest prune to give 2.5metres clearance from all structures (except fence), achieved by pruning any limbs back to main trunk of tree.



B – Elderberry and willow to side of 36 Fullshaw Bank, suggest prune to give 2.5metres clearance of all structures (except fence), achieved by pruning any limbs back to main trunk of tree.



C – Row of trees behind flat over a row of garages, 42 Mossley Place (not actually shown on the plan so marked location of building with a rectangle). Trees very close to guttering and must restrict light somewhat, suggest prune to give 2.5metre clearance from all structures (except fence), achieved by pruning any limbs back to main trunk of tree. Photo below shows view from front of property and also from within the woodland.



D – Sycamore and willow to side of 27 Mossley Place close to building, suggest prune to give 2.5metres from all structures (except fence), achieved by pruning any limbs back to main trunk of tree. Again the layout of the estate is not quite as shown on plan but the address is correct.



E – Willows to the side of 42 Mossley Place are close to the guttering at the rear of the property, suggest prune to give clearance of 2.5m from structures (except fence), achieved by pruning any limbs back to main trunk of tree.

