3 July 2012

Mr Arthur Wood
2 Old Mill Cottage
Roughbirchworth Lane
Oxspring
S36 8YE

Dear Mr Wood

TREE REPORT

Please find enclosed your completed tree survey for the above property.

If you require the recommended tree work carrying out, then please do not hesitate to contact us for a current quote.

Please also find enclosed your invoice for your records. We acknowledge your payment by cheque.

Thank you for using our services.

Kind regards

[redacted]

Vincent Nolan



Address:	2 OLD MILL COTTAGE OSPRING S36 8YE.
Client:	MR ARTHUR WOOD.

local
www. tree .co.uk
Office: 0114 236 3080
Sheffield Tree Services. 3 High Tree, Dore, Sheffield S17 3GF

Tree Ref T1 Location _____

Species LABURNUM

Height 5.5 (m) Truck girth 90 (cm) Crown Spread 6 (m)

Roots

Kinked or girdling roots Y/(N)

Signs of wounding Y/(N)

Basal flare Y/(N)

Fungi present Y/(N)

Any other constraints/objects NONE.

Trunk

Splits or cracks Y/(N)

Twisting Y/(N)

Physical damage Y/(N)

Any fungi present Y/(N)

Any other signs of damage PREVIOUS PRUNING CUTS NOT FULLY HEALED, IMPROPER CUTS MADE.

Canopy

Overall shape and appearance SLOW GROWTH ON ONE SIDE

Deadwood (Y)/N SOME TWIGS % 5

Epicormic growth present (Y)/N DUE TO PREVIOUS PRUNING.

Hazardous branches Y/(N)

Healthy looking leaves (Y)/N

Evidence of infestation Y/(N)

Healthy looking fruit (Y)/N

Tree Ref T2 Location _____

Species SYCAMORE

Height 17 (m) Truck girth 170 (cm) Crown Spread 8 (m)

Roots

Kinked or girdling roots Y (N) _____

Signs of wounding Y (N) _____

Basal flare Y (N) _____

Fungi present Y (N) _____

Any other constraints/objects LOTS OF SHRUBS MAKING ACCESS TO TRUNK DIFFICULT

Trunk

Splits or cracks Y (N) _____

Twisting Y (N) _____

Physical damage Y (N) _____

Any fungi present Y (N) _____

Any other signs of damage NONE

Canopy

Overall shape and appearance LOLLY POP - WEIGHTED RIGHT SIDE

Deadwood (Y) N MINIMAL % 1

Epicormic growth present (Y) N _____

Hazardous branches (Y) N OVERHANG TO NEIGHBOURS

Healthy looking leaves (Y) N _____

Evidence of infestation Y (N) _____

Healthy looking fruit (Y) N _____

Notes

Recommendations

REMOVE DEAD WOOD

CARRY OUT CROWN REDUCTION ESPECIALLY

ON OVERHANGING TO NEIGHBOURS

Risk Factor

2

1. Good Condition - monitor tree, no action required
2. Action Required - some basic work required
3. Hazardous Tree - work required see recommendations
4. Dangerous Tree - felling required

Notes TELEPHONE LINE THROUGH TREE.

Recommendations

REMOVE 4 SAPPLINGS AT BASE OF TREE.

REMOVE DEAD WOOD AND DANGEROUS BRANCHES

BALANCE CANOPY.

REMOVE BRANCHES AROUND TELEPHONE LINE

Risk Factor

2

1. Good Condition - monitor tree, no action required
2. Action Required - some basic work required
3. Hazardous Tree - work required see recommendations
4. Dangerous Tree - felling required

Tree Ref T3 Location _____

Species SYCAMORE

Height 19 (m) Truck girth 250 (cm) Crown Spread 12 (m)

Roots

Kinked or girdling roots Y (N) _____

Signs of wounding Y (N) _____

Basal flare Y (N) _____

Fungi present Y (N) _____

Any other constraints/objects NONE

Trunk

Splits or cracks Y (N) _____

Twisting Y (N) _____

Physical damage Y (N) _____

Any fungi present Y (N) _____

Any other signs of damage NONE

Canopy

Overall shape and appearance LARGE SPREAD EVENLY BALANCED

Deadwood (Y) N MINIMAL % 1

Epicormic growth present (Y) N _____

Hazardous branches (Y) N OVER HANGING ROAD

Healthy looking leaves (Y) N _____

Evidence of infestation Y (N) _____

Healthy looking fruit (Y) N _____

Notes

SIGNS OF NESTING.

IVY AROUND TRUCK AND GROUND

Recommendations

REMOVE IVY FROM TRUCK.

30% CROWN REDUCTION

REMOVE BRANCHES OR WEIGHT FROM BRANCHES OVERHANGING ROAD

Risk Factor

2

1. Good Condition - monitor tree, no action required
2. Action Required - some basic work required
3. Hazardous Tree - work required see recommendations
4. Dangerous Tree - felling required

Tree Ref T4 Location _____

Species LIME

Height 17 (m) Truck girth 210 (cm) Crown Spread 8 (m)

Roots

Kinked or girdling roots Y (N) _____

Signs of wounding Y (N) _____

Basal flare Y / (N) _____

Fungi present Y / (N) _____

Any other constraints/objects NONE

Trunk

Splits or cracks Y (N) _____

Twisting Y / (N) _____

Physical damage Y / (N) _____

Any fungi present Y (N) _____

Any other signs of damage NONE

Canopy

Overall shape and appearance HEALTHY LOOKING, BALANCED

Deadwood Y (N) _____ % _____

Epicormic growth present Y / (N) _____

Hazardous branches Y / (N) _____

Healthy looking leaves (Y) / N _____

Evidence of infestation Y / (N) _____

Healthy looking fruit (Y) / N _____

Notes

EVIDENCE OF BIRDS NESTING.

IVY ON TRUNK

Recommendations

REMOVE IVY GROWTH UP TRUNK

REDUCE HEIGHT OF TREE 20%

Risk Factor

2	1. Good Condition - monitor tree, no action required 2. Action Required - some basic work required 3. Hazardous Tree - work required see recommendations 4. Dangerous Tree - felling required

Tree Ref T5 Location _____

Species SYCAMORE

Height 14 (m) Truck girth 100 (cm) Crown Spread 6 (m)

Roots

Kinked or girdling roots Y / (N) _____

Signs of wounding Y / (N) _____

Basal flare Y / (N) _____

Fungi present Y / (N) _____

Any other constraints/objects NONE

Trunk

Splits or cracks Y / (N) _____

Twisting Y / (N) _____

Physical damage Y / (N) _____

Any fungi present Y / (N) _____

Any other signs of damage NONE

Canopy

Overall shape and appearance LIGHT DEPRIVED, WEIGHTED ONE SIDE.

Deadwood (Y) N MINIMAL % 2

Epicormic growth present (Y) N _____

Hazardous branches Y (N) _____

Healthy looking leaves (Y) N _____

Evidence of infestation Y / (N) _____

Healthy looking fruit (Y) N _____

Notes

Recommendations

*NOT DANGEROUS BUT RECOMMEND FELLING TO GIVE TREES EITHER SIDE SPACE TO GROW REMOVE 4 LIME SAPPLINGS AND REMOVE HAWTHORN BY ROAD

Risk Factor

4*	1. Good Condition - monitor tree, no action required 2. Action Required - some basic work required 3. Hazardous Tree - work required see recommendations 4. Dangerous Tree - felling required

Tree Ref T6 Location _____

Species SYCAMORE

Height 22 (m) Truck girth 210 (cm) Crown Spread 10 (m)

Roots

Kinked or girdling roots Y / (N)

Signs of wounding Y / (N)

Basal flare Y / (N)

Fungi present Y / (N)

Any other constraints/objects NONE

Trunk

Splits or cracks Y / (N)

Twisting Y / (N)

Physical damage Y / (N)

Any fungi present Y / (N)

Any other signs of damage NONE

Canopy

Overall shape and appearance BIG SPREAD HEALTHY

Deadwood (Y) / N MINIMAL % 1-3

Epicormic growth present Y / (N)

Hazardous branches Y / (N)

Healthy looking leaves (Y) / N

Evidence of infestation Y / (N)

Healthy looking fruit (Y) N

Notes

EVIDENCE OF NESTING

Recommendations

REDUCE IN HEIGHT, CROWN REDUCTION, 18 FT

LIME SPRING AT BASE OF TREE REMOVE.

REMOVE DEAD WOOD

Risk Factor

2

1. Good Condition - monitor tree, no action required
2. Action Required - some basic work required
3. Hazardous Tree - work required see recommendations
4. Dangerous Tree - felling required

Tree Ref T7 Location _____

Species SYCAMORE

Height 21 (m) Truck girth 190 (cm) Crown Spread 8 (m)

Roots

Kinked or girdling roots Y / (N)

Signs of wounding Y / (N)

Basal flare Y / (N)

Fungi present Y / (N)

Any other constraints/objects NONE

Trunk

Splits or cracks Y / (N)

Twisting Y / (N)

Physical damage Y / (N)

Any fungi present Y / (N)

Any other signs of damage NOSE AND NAILS EMBEDDED

Canopy

Overall shape and appearance TALL AND THIN SPREAD

Deadwood (Y) N MINIMAL % 2

Epicormic growth present Y / (N)

Hazardous branches Y / (N)

Healthy looking leaves (Y) / N

Evidence of infestation Y / (N)

Healthy looking fruit (Y) / N

Notes

Recommendations

REDUCE HEIGHT AND REMOVE DEAD WOOD

Risk Factor

2	1. Good Condition - monitor tree, no action required 2. Action Required - some basic work required 3. Hazardous Tree - work required see recommendations 4. Dangerous Tree - felling required

Tree Ref T8 Location _____

Species SYCAMORE

Height 16 (m) Truck girth 190 (cm) Crown Spread 8 (m)

Roots

Kinked or girdling roots Y / (N)

Signs of wounding Y / (N)

Basal flare Y / (N)

Fungi present Y / (N)

Any other constraints/objects NONE

Trunk

Splits or cracks Y / (N)

Twisting Y / (N)

Physical damage Y / (N)

Any fungi present Y / (N)

Any other signs of damage NONE

Canopy

Overall shape and appearance EVENLY BALANCED

Deadwood (Y) N MINIMAL % 2

Epicormic growth present Y / N

Hazardous branches (Y) N OVERHANGING ROAD

Healthy looking leaves (Y) / N

Evidence of infestation Y / (N)

Healthy looking fruit (Y) / N

Notes

SLIGHT LEAN

Recommendations

REDUCE IN HEIGHT AND CROWN REDUCTION

REMOVE BRANCHES OVERHANGING ROAD.

OR POSSIBLE FELL TREES DUE TO LEAN / HEIGHT RATIO

Risk Factor

2

1. Good Condition - monitor tree, no action required
2. Action Required - some basic work required
3. Hazardous Tree - work required see recommendations
4. Dangerous Tree - felling required

Tree Ref T9 Location _____

Species SYCAMORE

Height 17 (m) Truck girth 150 (cm) Crown Spread 7 (m)

Roots

Kinked or girdling roots Y / (N)

Signs of wounding Y / (N)

Basal flare Y / (N)

Fungi present Y / (N)

Any other constraints/objects NONE

Trunk

Splits or cracks Y / (N)

Twisting Y (N)

Physical damage Y / (N)

Any fungi present Y (N)

Any other signs of damage NONE

Canopy

Overall shape and appearance HEALTHY, WELL BALANCED

Deadwood (Y) / N MINIMAL % 2-4

Epicormic growth present Y (N)

Hazardous branches (Y) / N OVERHANGING ROAD

Healthy looking leaves (Y) / N

Evidence of infestation Y / (N)

Healthy looking fruit (Y) / N

Notes

Recommendations

CROWN REDUCE. REMOVE BRANCHES OVERHANGING ROAD

Risk Factor

2	1. Good Condition - monitor tree, no action required 2. Action Required - some basic work required 3. Hazardous Tree - work required see recommendations 4. Dangerous Tree - felling required

Tree Ref T10 Location _____

Species SYCAMORE

Height 20 (m) Truck girth 200 (cm) Crown Spread 10 (m)

Roots

Kinked or girdling roots Y / (N)

Signs of wounding Y / (N)

Basal flare Y / (N)

Fungi present Y / (N)

Any other constraints/objects NONE

Trunk

Splits or cracks Y / (N)

Twisting Y / (N)

Physical damage Y / (N)

Any fungi present Y / (N)

Any other signs of damage NONE

Canopy

Overall shape and appearance EVENLY BALANCED

Deadwood (Y) / N MINIMAL % 2

Epicormic growth present Y / (N)

Hazardous branches (Y) / N LARGE OVERHANGING LIMB

Healthy looking leaves (Y) / N

Evidence of infestation Y / (N)

Healthy looking fruit (Y) / N

Notes

Recommendations

REDUCE HEIGHT AND OVERHANGING BRANCHES.

Risk Factor

2	1. Good Condition - monitor tree, no action required 2. Action Required - some basic work required 3. Hazardous Tree - work required see recommendations 4. Dangerous Tree - felling required