




1. Looking towards the access to 'Plot B' – Gladman's Development Site.




2. View looking at the end of Wentworth Way with the site access on the right.



3. Looking towards the site access, note the poor condition of the carriageway surface.




4. Kerb line of footway approaching the site entrance.




5. BT Joint Box in f/w near site entrance – note existing condition of f/w.




6. Sewer cover in hammer head nr site entrance.



7. Footway on left hand side of carriageway approaching site entrance.



8. Damaged Street Light outside 'Cranes UK' – 1-4 Wentworth Way.



9. Existing damage to footway opposite site entrance.



10. Carriageway cracking surrounding manhole cover near site entrance.



11. Carriageway cracking surrounding manhole near site entrance.