


Notes
Check all dimensions on site. Do not scale from this drawing.
Report any discrepancies and omissions to HLM Architects
This Drawing is Copyright ©

- KEY
- Existing walls - Historic
 - Existing walls - Recent
 - Infill to existing wall openings
 - Proposed new walls
 - Extent of proposed works

With the exception of the first floor lettable space shell which shall be complete by the tenant, all existing walls should be made good and redecorated, including but not limited to, plastering exposed masonry, filling and sanding cracks and holes, removing flaking paint, caulking gaps to joinery. Areas of infill wall should receive new skirtings and cornice where applicable to match existing.



C03 Existing corridor sub-divided with new partition and door. Existing opening infilled with steel partition.	12/12/2023	JHH	AJT
C02 Cleaners cupboard and key arrangement amended.	06/06/2023	MSD	AJT
C01 STAGE 3 ISSUE	09/01/2023	MSD	AJT
P07 STAGE 4 ISSUE	05/08/2022	MSD	AJT
P06 Accessible WC moved. Notes added/amended.	22/07/2022	MSD	AJT
P05 Lift moved. Stair 02 width increased.	01/07/2022	MSD	AJT
P04 Hanson Street rooms amended.	15/06/2022	MSD	AJT
P03 STAGE 3 ISSUE	06/05/2022	MSD	AJT
P02 Notes added/amended.	07/04/2022	MSD	AJT
P01 Preliminary issue.	11/03/2022	MSD	AJT

Rev	Description	Date	By	Chk
Revisions				Suitability
Project				A5 CONSTRUCTION

11-1177-01
BARNSELY CIVIC
ENTERPRISE

Client
BARNSELY CIVIC
ENTERPRISE

Title
Third Floor Proposed Plan

Drawing No.	Revision
BCE-HLM-01-03-DR-A-00154	C03

Scale	Drawn
1 : 100 @A0	MSD
Date	Checked
11/03/2022	AJT