

PHOTOGRAPHIC SURVEY



Fig 01. View of access and adjacent garages and parking on Spout House Lane looking south.



Fig 02. View of existing access with Stables to rear.



Fig 03. North East Elevation of stables.




Fig 4 and 5. NE Elevation of Tack Room and Store.



Fig 6. View of stables and workshop looking south.



Fig 7. Exercise area to front (north) of stables, looking south west.