LEGEND

- Foul Drainage
- Surface Drainage
- Combined Drainage
- Electricity
- Electricity High Voltage
- Electricity Low Voltage
- Gas
- Ground Probing Radar
- Water
- Cable Television
- Close Circuit Television
- Communication
- British Telecom
- Compressed Air
- Offset Fill-Line
- Oil Pipe
- Pipe
- Ventilation
- Fuel Line
- Vapour Recovery
- Gauge Line
- Telemetry
- Fibre Optics
- Unknown
- Fence
- Edge of Canopy
- Gully Run
- Electricity (TFR) Taken From Records
- BT (TFR) Taken From Records
- Gas (TFR) Taken From Records
- Water (TFR) Taken From Records
- End Of Trace
- Do Not Drill / Banded Pipes
- T TANK* - W= Water U=Unknown F=Foam P=Product C=Concrete
- Borehole
- Trial Pit Location
- Excavated Area
- Window Sample
- Soil Vapour Sample

ABBREVIATIONS

AR	Assumed Route	MW	Monitoring Well
BO	Bollard	NPV	No Pipes Visible
BO/ILL	Illuminated Bollard	OH	Overhead Service
BH	Borehole	OSA	Off Survey Area
BTB	British Telecom Box	OSBM	Ordnance Survey Bench Mark
BTIC	British Telecom Cover	PR	Pipe Riser
C/BOX	Control Box	P	Post
C/B FENCE	Closeboard Fence	P&R FENCE	Post & Rail Fence
CR	Cable Riser	RET WALL	Retaining Wall
CATV	Cable TV	RWP	Rain Water Pipe
CP	Catch Pit	RS	Road Sign
Co	Concrete	RE	Rodding Eye
CON	Conifer	S/A	Soakaway
CL	Cover Level	S/BIRCH	Silver Birch
d	Depth (in metres)	SAP	Sapling
D/CHAN	Drainage Channel	SEC FENCE	Security Fence
DP	Down Pipe	SL	Spot Light
ER	Earth Rod	SP	Soil Pipe
EIC	Electricity IC	ST	Stop Tap
EP	Electricity Pole	SV	Sluice Valve
EOC	Edge of Canopy	SVP	Soil Vent Pipe
EOT	End of Trace	SVS	Soil Vapour Sample
F/BED	Flower Bed	TBM	Temporary Bench Mark
FH	Fire Hydrant	TFR	Taken From Records
FS	Fire Switch	TL	Traffic Light
GV	Gas Valve	TP	Telegraph Pole
G	Gully	TS	Traffic Sensor
GPR	Ground Probing Radar	UTL	Unable to Locate
G/RUN	Gully Run	UTR	Unable to Raise
HT	Height	UTS	Unable to Survey
H/CHESTNUT	Horse Chestnut	UTT	Unable to Trace
H/THORN	Hawthorn	VR	Vapour Recovery
IC	Inspection Cover	VP	Vent Pipe
IL	Invert Level	WM	Water Meter
INT	Interceptor	WFC	Water Filled Chamber
KO	Kerb Outlet	WP	Waste Pipe
LP	Lamp Post	WR	Water Riser
LC	Lighting Column	WS	Window Sample
LH	Lamp Hole	U/S	Underside
MH	Manhole Cover	Ø	Pipe Diameter

General Notes:

Some services may go undetected where active connections cannot be applied.

AVOIN MAA SURVEYS LTD

32 Doncaster Road, Barnsley, South Yorkshire, S70 1TL.
Tel: 01226 292 377 Mobile: 07969 360287
E-Mail: scott@avoinmaasurveys.com & info@avoinmaasurveys.com
Website: www.avoinmaasurveys.com

Client

Ian Falkingham

Site Location

2 St John's Close
Dodworth
Barnsley, S75 3RY

Surveyed by AC	Drawn by AC	Approved by -
Drawing No. (Not Applicable)		Revision -
Scale 1:100@ A1	Date 06/7/2026	Sheet No. 1 of 1

DISCLAIMER: The location of under ground services shown on this drawing has been determined using electro-magnetic (and/or ground probing radar, where requested) techniques and visual observations. the limitations of this drawing should be realised and no guarantee can be given that all services have been identified. This drawing may not include the location of all public services that may cross the site and therefore the relevant service drawings should be obtained from the appropriate utility company and used in conjunction with this drawing. Additional services, structures or other below ground obstructions not indicated on this drawing may be present on site. reference should be made to historical plans and as built drawings. Excavations in the vicinity of services should be carried out with due diligence ref: HSG47 document "avoiding dangers from underground services". Location accuracy is determined by refering to manufacturers guidelines for the systems deployed. Reference should be made to the latest version of AMS Ltd site procedures document for utility location surveys Please note ground penetrating radar depths are approximate only.