

647697 Tesco Maintenance Hoyland

Trees overgrown and blocking sign gantry - Mix of hazel and other vegetation has grown up in front of the sign, It will be cut back to the fence (approximately 2m back) to just above the sign, (approximately 4m). This will be 5m either side of the sign.

