

Photograph 3: Stable in the north. Photograph taken facing north.



Photograph 4: Stables in the north. Photograph taken facing east.



Photograph 5:Hay barn in western end of site. Photograph taken facing west.



Photograph 6: Scaffold storage area in the northwest corner of the site.



Photograph 7: Bales of straw in eastern end of the site. Photograph taken facing north towards the stables



Photograph 8: Pile of manure towards the southern end of site. Photograph taken facing south.



Photograph 9: Farm machinery in the southern end of the site.



Photograph 10: Mound of rubble towards the southwestern boundary of the site.