

Appendix B: Site Walkover Photographs

This page has been left intentionally blank.



Job: Phase 1 Site Investigation
Site: Land to the Rear of 26 Cross Lane, Royston
Ref: 8771

Current site access to the side of No. 26 Cross Lane.



Job: Phase 1 Site Investigation
Site: Land to the Rear of 26 Cross Lane, Royston
Ref: 8771

View along track in northern part of the site, facing east towards the stable building.

ECUS Ltd
Brook Holt
3 Blackburn Road
Sheffield. S61 2DW

Tel : (0114) 2669292
www.ecusltd.co.uk





Job: Phase 1 Site Investigation
Site: Land to the Rear of 26 Cross Lane, Royston
Ref: 8771

Barn in the northern part of the site, facing south.



Job: Phase 1 Site Investigation
Site: Land to the Rear of 26 Cross Lane, Royston
Ref: 8771

Stables and barn in the northern part of the site, facing south-west.

ECUS Ltd
Brook Holt
3 Blackburn Road
Sheffield. S61 2DW

Tel : (0114) 2669292
www.ecusltd.co.uk





Job: Phase 1 Site Investigation
Site: Land to the Rear of 26 Cross Lane, Royston
Ref: 8771

Brick building in the northern part of the site, housing ducks. Facing west.



Job: Phase 1 Site Investigation
Site: Land to the Rear of 26 Cross Lane, Royston
Ref: 8771

Stable in the north-eastern corner of the site, facing east.

ECUS Ltd
Brook Holt
3 Blackburn Road
Sheffield. S61 2DW

Tel : (0114) 2669292
www.ecusltd.co.uk

