411340N

411320N

411300N

411280N

411260N

411240N

440860E

Client To Maintain Access To Green Space

GREENBELT

TYPE A 5.

TYPE A 4.

TYPE B 3.

TYPE B 2.

TYPE 1.

Barn 2 annex plot 5

Barn 1 annex plot 1

ORIGINAL STONE QUOINS

PART OF BARN TO BE DEMOLISHED AS AGREED ON SITE WITHN TONY WILES

PARKING PLOT 5

PARKING PLOT 1

Garage

21M

4.5m private drive

RELOCATED POND- REFER TO ECOLOGY APPRAISAL

STONE WALL SET BACK AND REBUILT IN RECLAIMED STONE TO MATCH EXISTING

Footpath

Driveway

Pond

Hedgerow

Dense Bushes

Conc Bollards

Notional Wall Position

Root Line

Ridge 1.9m

Ridge 1.8m

Ridge 1.7m

Ridge 1.6m

Ridge 1.5m

Ridge 1.4m

Ridge 1.3m

Ridge 1.2m

Ridge 1.1m

Ridge 1.0m

Ridge 0.9m

Ridge 0.8m

Ridge 0.7m

Ridge 0.6m

Ridge 0.5m

Ridge 0.4m

Ridge 0.3m

Ridge 0.2m

Ridge 0.1m

Ridge 0.0m

Ridge 0.0m +0.7m Gable

Stwl 1.8h

Stwl 1.2h

Stwl 0.9h

Stwl 0.8h

Stwl 0.6h

Stwl 0.3h

Stwl 0.0m

Stwl Footings 0.1h

Stone Arch on Bk/wl

Timber box over steps Possible underground bunker?

Stone Steps

Flags

Grass

Bushes

Trees

Vegetation

Plants

Plants/ Bushes

Overgrown Ruins/ Debris

Bush/ Vegetation

Topped Tree

Hedge

Fence

Conc

Tmac

Debris

Thresh

Step

Ramp

Slope

Pavement

Manhole

Gully

Catchpit

Bollard

Bench

Post

Sign

Pylon

Pipe

Wall

Bank

Ditch

Kerb

Edge

Channel Blocks

Rock Outcrop

Rubble/Veg

Pavin (Dilapidated)

Conifer

Bush

Pond

Stone Wall

Timber Fence

Metal Fence

Hedgerow

Bushes

Grass

Tmac

Trees

Vegetation

Dense Bushes

Notional Wall Position

Root Line

Ridge 1.9m

Ridge 1.8m

Ridge 1.7m

Ridge 1.6m

Ridge 1.5m

Ridge 1.4m

Ridge 1.3m

Ridge 1.2m

Ridge 1.1m

Ridge 1.0m

Ridge 0.9m

Ridge 0.8m

Ridge 0.7m

Ridge 0.6m

Ridge 0.5m

Ridge 0.4m

Ridge 0.3m

Ridge 0.2m

Ridge 0.1m

Ridge 0.0m

Ridge 0.0m +0.7m Gable

Stwl 1.8h

Stwl 1.2h

Stwl 0.9h

Stwl 0.8h

Stwl 0.6h

Stwl 0.3h

Stwl 0.0m

Stwl Footings 0.1h

Stone Arch on Bk/wl

Timber box over steps Possible underground bunker?

Stone Steps

Flags

Grass

Bushes

Trees

Vegetation

Plants

Plants/ Bushes

Overgrown Ruins/ Debris

Bush/ Vegetation

Topped Tree

Hedge

Fence

Conc

Tmac

Debris

Thresh

Step

Ramp

Slope

Pavement

Manhole

Gully

Catchpit

Bollard

Bench

Post

Sign

Pylon

Pipe

Wall

Bank

Ditch

Kerb

Edge

Channel Blocks

Rock Outcrop

Rubble/Veg

Pavin (Dilapidated)

Conifer

Bush

Pond

Stone Wall

Timber Fence

Metal Fence

Hedgerow

Bushes

Grass

Tmac

Trees

Vegetation

Dense Bushes

Conc Bollards