


LANCASTER STREET



1 Structural defect




4 Surface fretting



7 Surface cracking



2 Structural defects



5 Road widening / Surface defects



8 Surface fretting



3 Structural defects



6 Trench failure



9 Road widening



10 Structural failure around manhole



13 Structural failure



16 Structural failure around manhole



11 Trench failure



14 Surface Cracking



17 Surface fretting



12 Surface fretting



15 Trench failure



18 Surface fretting



19 Surface fretting



22 Structural failure



25 Surface fretting



20 Structural failure



23 Structural failure



26 trench failure



21 Structural failure



24 Surface fretting



27 Structural failure



28 Structural failure around manhole



31 Trench failure




34 Surface fretting



29 Surface defect



32 Surface fretting



35 Surface fretting



30 Surface defect / cracking



33 Surface fretting



36 Surface defect / cracking



37 Structural failure around manhole



40 Structural defect



43 Surface fretting



38 Trench failure



41 Surface defect



44 Surface fretting



39 Trench failure



42 Surface fretting



45 Surface fretting



46 Trench failure



49 Concrete ramps



52



47 Trench failure



50 Surface fretting



53 Surface defects



48 Concrete ramps



51 Trench failure



54 Structural failure around gully



55 Trench failures



56 Structural failure around manhole



57 Trench failure