

PHOTOGRAPHIC SURVEY



01. View of access lane looking north



02. View of access lane looking south



03. View of entrance to site from access lane.



04. View of site from Access Lane looking north east.



05. Existing bungalow – front west elevation.



06. Existing bungalow – front west and side north gable elevation.



07. Existing Bungalow rear east elevation.



08. Rear conservatory – east elevation.



09. Conservatory side north elevation.



10. Traditional roof structure of rafters and timber purlins onto blockwork supports.