
TIVY DALE
Tarmac Footpath
Stone Wall
Bushes & Shrubs
Grass
Gate
Ridge
94.28
MH
Kerb
Eaves
93.70
Eaves
93.71
Ridge
95.15
Ridge
95.19
Tarmac
SV
ST03
88.74
New Dropped Kerb
Gate Post
Eaves
92.36
Ridge
96.80
Kerb
Tarmac Footpath
ST02
88.52
O/H Wire
BT
88.97
89.19
Unable to Survey
Boundary Position
Due to Overgrowth
88.94
PIR Fence
PIR Floodlight
Tree Canopy Line
Overgrown
ST08
89.35
ST06
89.20
ST05
89.16
Concrete
Garage
Unable to Survey
Overgrown
89.72
ST07
90.72
90.55
90.65
90.85