

LEVEL MONITORING

for Subsidence Management Services

Two Oaks, 152 Intake Lane, Barnsley, S75 2HU

Client:	Subsidence Management Services
Client Contact:	Mauro Loscalzo
Claim Number:	4502063050
Client Reference:	IFS-AVI-SUB-22-0101673
Policy Holder:	Mr Ian Clifton
Report Date:	30 November 2022
Our Ref:	M19305

Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5	6	7	8	9	10
19/09/2022	10.0000	9.9137	9.8898	9.9004	9.8249	9.8959	9.9217	10.0000	9.9573	9.9925
25/11/2022	10.0000	9.9172	9.9017	9.9085	9.8270	9.8967	9.9289	10.0008	9.9637	9.9945



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

TBM is station one and assumed to be a value of 10.0000m no secondary found please advise if deep datum is required, relative survey

Site Visit: 19 September 2022

40 minute level