

# Trial Pit Photos

TP05

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 40: TP05 arisings. (1).



Photograph 41: TP05 arisings. (2).

# Trial Pit Photos

TP05

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 42: TP05 arisings. (3).



Met Consultancy Group Ltd  
 Southgate House  
 Pontefract Road  
 Leeds  
 LS10 1SW  
 Email: admin@metconsultancygroup.com  
 Phone: 0113 200 8900

# Trial Pit Log

TrialPit No  
 TP06  
 Sheet 1 of 1


Project Name: Parkside Sports and Community Centre, Hoyland

Project No.  
 P22-01115

Co-ords: 435947.22 - 399774.71  
 Level:

Date  
 16/12/2022

Location: Land between Sheffield Road and Stead Lane, Hoyland, Barnsley, S74 0AH



Scale  
 1:25

Logged  
 YK

Client: Barnsley Metropolitan Borough Council

Water Strike	Samples & In Situ Testing			Depth (m)	Level (m)	Legend	Stratum Description
	Depth	Type	Results				
				0.50			Grass overlying dark brown silty slightly sandy slightly gravelly CLAY (TOPSOIL).
				1.20			MADE GROUND: Orangish brown mottled grey silty sandy gravelly CLAY with a moderate cobble content. Sand is fine to coarse. Gravel is angular to subangular fine to coarse of mixed lithologies including siltstone, sandstone, mudstone and coal. Cobbles are subangular of sandstone and siltstone. Occasional roots noted.
				2.80 2.80			OPENCAST FILL: Grey cobbles and boulders in a clayey sand and gravel matrix. Sand is fine to coarse. Gravel is angular to subangular fine to coarse of mixed lithologies including sandstone, siltstone, mudstone. Cobbles and boulders are angular to subangular of sandstone, siltstone and mudstone up to 2.2m across. Whole brick noted.
							Brown SILTSTONE/SANDSTONE bedrock. Potential 'steps' in bedrock noted in western extents of trial pit at a top depth of 1.2mbgl. End of Pit at 2.80m

Remarks: Trial pit terminated and backfilled due to collapse of unstable trial pit sides as a result of opencast backfilling.

Stability: Unstable due to opencast backfill.

Weather:

Clear

# Trial Pit Photos

TP06

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 43: Trial pit TP06. Western face of trial pit, view from the east to the west.



Photograph 44: Trial pit TP06. Western face of trial pit, view from the north east to the south west.

# Trial Pit Photos

TP06

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 45: Trial pit TP06. Eastern face of trial pit, view from the west to the east.



Photograph 46: Trial pit TP06. Collapse of unstable trial pit sides due to opencast backfilling.

# Trial Pit Photos

TP06

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 47: TP06 arisings. (1).



Photograph 48: TP06 arisings. (2).

# Trial Pit Photos

TP06

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 49: TP06 arisings. (3).