



**Job:** Phase 1 Site Investigation  
**Site:** Land to the Rear of 26 Cross Lane, Royston  
**Ref:** 8771

**Pile of general waste in front of the stables, facing north.**



**Job:** Phase 1 Site Investigation  
**Site:** Land to the Rear of 26 Cross Lane, Royston  
**Ref:** 8771

**Circular structure (possible former drinking trough) in the northern part of the site, facing south.**

ECUS Ltd  
Brook Holt  
3 Blackburn Road  
Sheffield. S61 2DW

Tel : (0114) 2669292  
[www.ecusltd.co.uk](http://www.ecusltd.co.uk)





**Job:** Phase 1 Site Investigation  
**Site:** Land to the Rear of 26 Cross Lane, Royston  
**Ref:** 8771

Suspected asbestos cement sheets propped against stables in north-east of site, facing north-west.



**Job:** Phase 1 Site Investigation  
**Site:** Land to the Rear of 26 Cross Lane, Royston  
**Ref:** 8771

Internal view of stables building in north-eastern corner of the site, facing north-east.

ECUS Ltd  
Brook Holt  
3 Blackburn Road  
Sheffield. S61 2DW

Tel : (0114) 2669292  
[www.ecusltd.co.uk](http://www.ecusltd.co.uk)

 **ecus**  
ENVIRONMENTAL CONSULTANTS



**Job:** Phase 1 Site Investigation  
**Site:** Land to the Rear of 26 Cross Lane, Royston  
**Ref:** 8771

**Paddock in the eastern part of the site, facing south.**



**Job:** Phase 1 Site Investigation  
**Site:** Land to the Rear of 26 Cross Lane, Royston  
**Ref:** 8771

**View across southern half of the site, facing west towards Cross Lane.**

ECUS Ltd  
Brook Holt  
3 Blackburn Road  
Sheffield. S61 2DW

Tel : (0114) 2669292  
[www.ecusltd.co.uk](http://www.ecusltd.co.uk)



## **Appendix C: Historical Ordnance Survey Maps**

This page has been left intentionally blank.