

Stairfoot Highways Survey - POST CONSTRUCTION									
---	--	--	--	--	--	--	--	--	--

Company	Ginger Lehmann								
Survey Date	19th January 2023								

Section ID	Network Length	End: Lanes Present	Project	Road Name	Speed Limit	Start Time	End Time	Surveyed Length	Surveyor
Oak001	177	2	GB2019.10667	Tank Row and Oaks Lane	30	44945.68332	44945.69454	182	jkc

Carriageway									
Section ID	XSP	Start Chainage	End Chainage	Start Surface	End Surface	Notes			
Oak001	CL1	0	182	BIT	BIT				
Oak001	CR1	0	182	BIT	BIT				

Major Defects									
Section ID	XSP	Start Chainage	End Chainage	Start Cracked Wheel Tracks	End Cracked Wheel Tracks	Start Lateral Extent	End Lateral Extent	Notes	
Oak001	CL1	31	34	0	0	Single Crack	Single Crack		
Oak001	CL1	147	180	1	1	25%	25%		
Oak001	CR1	156	180	1	1	25%	25%		

Minor Defects									
Section ID	XSP	Start Chainage	End Chainage	Start Lateral Extent	End Lateral Extent	Notes			
Oak001	CL1	68	135	Isolated	Isolated				
Oak001	CR1	66	138	Isolated	Isolated				



Stairfoot

Highway Survey
Oaks Lane plus 30m of Tank Row

Legend

- Highways Survey
- Stairfoot Site



Stairfoot Highway Survey of Oak Lane & 30m of Tank Row 2023















