	**Photograph 13 (facing W):** Garage roof possibly containing ACMs.
	**Photograph 14 (facing W):** Garage roof possibly containing ACMs.

APPENDIX F

TRIAL HOLE LOGS

TH1

Brown sandy topsoil with brick and concrete fragments. Large brick fragments, up to 10cm in diameter.

TH2

Brown sandy topsoil with brick and concrete fragments within the soil.

TH3

Brown sandy topsoil with brick and concrete fragments within the soil.