NE 853.

BARROW COLLIERY WORKINGS
Abandonment Plan No. NE. 662
Abandoned 23rd. November, 1968

BARRIER BETWEEN ROCKINGHAM & BARROW COLLIERIES

WOMBWELL MAIN COLLIERY WORKINGS
Abandonment Plan No. NE. 552
Abandoned 30th. June, 1965

Boundary between Rockingham and Wombwell Main Collieries

BARROW FAULT

ASSUMED WATERLOGGED

This plan is a true copy of the working plan of the mine as completed up to 26-11-1977 and I certify after thorough examination and enquiry that to the best of my knowledge and belief it is an accurate plan of the mine.
Signed R. Shaw Surveyor
Date 3-2-81
Certificate N° 1802 Dated 30-9-1946

I hereby certify that no further working has taken place after the date of abandonment which would affect the accuracy of this plan.
Signed [illegible] Manager
Date 3. 2. 81
Certificate N° 8048 Dated 28-11-1960

SILKSTONE SHAFT
THORNCLIFFE SHAFT
LIDGETT SHAFT
HOYLAND SILKSTONE COLLIERY
N.C.B.

Roadways in Low Fenton Seam
Roadway in Parkgate Seam
Roadways in Parkgate & Low Fenton Seams
Roadway in Thornecliffe Thin Seam
Roadway in Thin Seam
Roadway in Low Fenton Seam
Roadway in Whamcliffe Silkstone Seam
Roadway in Phillips Seam

Parkgate Seam
Low Fenton Seam
Thornecliffe Thin Seam
Thin Seam

Not known
Not known 22 yds.
Not known 10 yds.
Not known 6 yds.
Not known 4 yds.
Not known 4½ yds.

Pond
School
Church Street
St. Georges Church
Wood Walk
Rockingham Road
Barnsley Road
Hawshaw Lane
March 1903
June 1906
June 1908
June 1909
June 1911
June 1917

ROCKINGHAM COLLIERY

	No. 1 SHAFT 44/3501/277005	No. 2 SHAFT 44/3501/300036	HOYLAND SILKSTONE SHAFT 44/3601/956483	SKIERS SPRING SHAFT 43/3699/731189
SURFACE LEVEL	10421·10	10418·43	10465·00	10338·90
SWALLOW WOOD SEAM LEVEL	10352·44	10349·77	9916·00	10240·24
LIDGETT SEAM LEVEL	10145·99	10126·90		10047·41
JOAN SEAM LEVEL				
FLOCKTON THICK SEAM LEVEL	9922·89	9907·80		
FLOCKTON THIN SEAM LEVEL				
TOP FENTON SEAM LEVEL	9756·40	9741·31	9319·00	9711·41
LOW FENTON SEAM LEVEL	9746·00	9731·91	9311·00	
PARKGATE SEAM LEVEL	9685·92	9671·83	9254·00	9638·75
THORNCLIFFE THIN SEAM LEVEL	9587·52	9573·83	9168·00	9580·58
INSET LEVEL	9514·35			
SILKSTONE SEAM LEVEL	9418·60	9410·00	8940·00	9341·58
DEPTH OF SHAFT	355·27 yds	336·14 yds	508·33 yds	348·70 yds

WHARNCLIFFE SILKSTONE COLLIERY

	No. 1 SHAFT 43/3399/765774	No. 3 SHAFT 43/3399/750811	No. 4 SHAFT 43/3399/732750	SURFACE DRIFT 43/3399/731675
SURFACE DECKING LEVEL	10504·40		10500·10	
SURFACE LEVEL	10484·90	10483·40	10488·40	10490·30
TOP FENTON INSET LEVEL	10373·00	10367·00	SEAM 10387·40	SEAM 10418·70
PARKGATE SEAM INSET LEVEL	10303·00	10297·00	SEAM 10314·90	
THORNCLIFFE THIN INSET LEVEL	10219·00	10213·40	10232·80	
SILKSTONE SEAM INSET LEVEL	10032·10		10044·70	
WHINMOOR SEAM LEVEL			9850·00	
WHINMOOR INSET LEVEL			9842·20	
DEPTH OF SHAFT	162·00 yds.	91·00 yds.	225·00 yds	LENGTH 102·00 yds

44/3601

ROCKINGHAM COLLIERY
INCORPORATING WHARNCLIFFE SILKSTONE COLLIERY
AS FROM 1st. AUG. 1967

-SCALE - 1/2500-

DATUM FOR LEVELS
10000 feet below ORDNANCE DATUM

SCALE OF METRES
100 50 0 100 200

SCALE OF FEET
100 0 100 300 500 700 900

TYPICAL — SECTION OF SEAM —

SHALE
COAL 10'
DIRT 6'
COAL 2' 8'
DIRT 1'
COAL 8'
SPAVIN

TOP FENTON SEAM

DATE OF ABANDONMENT 26th NOVEMBER, 1977
DATE OF CONSTRUCTION OCTOBER, 1955

The Coal Authority

Catalogue No.: NE853 Sheet Info:

Date: 24/05/2016 Scale: 1 TO 2500

Database Right and Copyright, The Coal Authority 2003, Unauthorised Use Prohibited

Jack Elsome - Delta Simons,3 Henley Office Park,Doddington Road,Lincoln,LN6 3QR,United Kingdom

All rights reserved. No part of any image supplied may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without the prior written permission of the Authority. By accepting and using this image you agree to be bound, without limitation or qualification, by the terms and conditions for the use of the Coal Authority Scanning Services which can be viewed at: www.coal.gov.uk/services/history/tc