

TREE WORK APPLICATION

1 Applicant

Mr D Jones
'Roundhills'
Redbrook Road
Barnsley
S75 2RS
Tel: 01226 248679

2 The TPO

I wish to apply to BMBC for consent to carry out work on trees protected by a TPO

TPO number: 7/90

3 The Trees and My Interest

The trees are at the address above and I am the owner of the land

4 The Application


- a) The oak tree marked T1 on plan
- b) The three holly trees marked T2, T3 and T4 on plan
- c) The cypress tree marked T5 on plan

The proposed operations are to fell and completely remove all five trees

Five years ago damage (in the form of cracking-both internal and external) to the bungalow occurred and was investigated professionally (see attached copy letter Cunningham Lindsey) and four of these trees identified as the likely cause of the problems. Some remedial work was carried out to the property to both fill in and try to prevent further cracking (mesh reinforcement to part of wall) in 2006. Since then further damage in the form of cracking has gradually occurred-see photographs of current state of damage across several rooms.

5 Plan

(SEVERAL OTHER MATURE TREES ARE
IN THIS AREA)



Signed:

Mr D Jones
9th January 2011

