

70 Woodheys Drive
Sale
Cheshire
M33 4JD



Willmott Dixon Construction Ltd

The Seam, Barnsley.


Dilapidation Survey.

12th March 2026.

The condition survey was carried out on 12th March 2026

The list below is the sequence of how the survey was carried out, the numbering shows the file location followed by the description of the areas, as identified in the drawings below.






1A-1B - County Way - Kerbs and Footpath

2A-2B - County Way - Kerbs and Footpath

3A-3B - County Way - Road Surface



1A-1B - County Way - Kerbs and Footpath

2A-2B - County Way - Kerbs and Footpath

3A-3B - County Way - Road Surface

4A-4B - South Entrance - Kerbs and Footpath

5A-5B - South Entrance - Kerbs and Footpath

6A-6B - South Entrance - Road Surface