



These photographs were taken on 26/04/2022 and are a true reflection of the site circumstances on that date.

Top row: site view looking south-east; site view looking north-west; site condition and boundary wall; boundary wall

Middle row: site entrance/boundary with footpath beyond; footpath adjacent to site; site entrance from Delph Mews

Bottom row: view from the site to the north-east; view of 1 Delph Mews from the site