ROOT IDENTIFICATION

for Subsidence Management Services

23 Oakfield Walk, Barnsley, S75 2LW

Client:	Subsidence Management Services
Client Contact:	John Buckley
Claim Number:	500061895
Client Reference:	IFS-LBG-SUB-18-0078492
Policy Holder:	Mr Rob Bramley
Report Date:	25 April 2022
Our Ref:	R44981

Intec
Parc Menai, Bangor,
Gwynedd, North Wales
LL57 4FG
Tel: 01248 672652

Sub Sample	Species Identified		Root Diameter	Starch
BH3:				
0.3-1.3m	probably *Quercus* spp.		1 mm	Low
0.3-1.3m	*Populus* or *Salix* spp.	1	<1 mm	Low
1.3-2.1m	*Quercus* spp.	2	3 mm	Moderate
1.3-2.1m	broadleaved species, too decayed for positive identification		3 mm	Absent
BH4:				
0.3-1.3m	either *Quercus* spp. or *Castanea* spp.	3	<1 mm	Absent
1.3-2m	probably either *Quercus* spp. or *Castanea* spp.	4	<1 mm	Absent
1.3-2m	too small and decayed for identification	5	<1 mm	Absent

Comments:

1 - Plus 2 others the same. All small and juvenile.
2 - Plus 2 others also identified as *Quercus* spp.
3 - Plus 3 others the same. All juvenile and in a state of decay.
4 - Very small and decayed.
5 - Plus 2 others the same.

Quercus spp. are oaks. *Castanea* spp. include sweet chestnut.
Populus spp. are poplars and aspen; *Salix* spp. are willows.

Signed: R J Shaw

Unless we are otherwise instructed in writing, the above sample material will normally be disposed of 6 years after the date of this report.

INVESTOR IN PEOPLE
Registered in England No. 295427 Registered Office: Unit 4 Linnet Court, Cawledge Business Park, Alnwick, NE66 2GD
ISO 9001