

## Existing Material Features

To be viewed in conjunction with supporting and heritage statement and existing & proposed elevations.

The Fitzwilliam Arms No42

Hill Street

Elsecar



## Brickwork and Features

- Facade brickwork showing Flemish bond pattern.
- Tie bar ends to be reinstated in the same locations.
- Window heads and cills to be restored.



## Stone Door Surround

- Images showing crests and profiles.
- Surround to be sent off for specialist restoration.
- To be painted black as existing.



## Front Door

- Front door to be restored, painted black and reinstated on rebuilt elevation.
- No42 restored and reinstated.
- Door knob to be restored and instated

