

PHOTOGRAPHIC SURVEY



01. View of site and access from Church Street



02. Road frontage with Chantry House on left hand side.



03. Barn - North East Elevation



04. North East and North West Elevation taken before ivy removal.



05. Rear wall of barn – North East Elevation.



06. Rear Wall of barn – North East Elevation