Site Photographs



View of northeast corner of site and adjacent property from Barnsley Road



View of southwestern corner of site and dense vegetation from Barnsley Road



Relatively open and clear northern area of site looking west



Northeast quarry face – exposed and devoid of vegetation



View towards southwestern corner of site



View of northwestern quarry face - densely overgrown with vegetation



Evidence of fly tipping within central southern area of site



Evidence of fly tipping within northeastern area of site



Remnant structures adjacent to northern quarry face