






Rear Elevation

The existing fence line has been installed incorrectly, encroaching over the boundary towards No 65. This to be demolished prior to construction.



Side Elevation on 2



Side Elevation on 1

Existing Elevations

1 : 100 @ A3