ELDON ARCADE

BARNSLEY INTERCHANGE
COACH STATION

MIDLAND STREET

MIDLAND STREET

SCHWABISCH GMUND WAY

SCHWABISCH GMUND WAY

BINGO CLUB

EXISTING BUILDING

KENDRAY STREET

KENDRAY STREET

JUMBLE LANE CROSSING

OPEN
MARKET

SERVICE AREA

NO ENTRY

BUS STOP

LOOK LEFT

LOOK RIGHT

KEEP CLEAR

KEEP CLEAR

UNABLE TO SURVEY DUE TO OVERGROWN VEGETATION

UNABLE TO SURVEY DUE TO OVERGROWN VEGETATION

APPROXIMATE POSITION OF TRACK SURVEYED REMOTELY

APPROXIMATE POSITION OF TRACK SURVEYED REMOTELY

## Notes

This drawing and the information contained therein is issued in confidence and is the copyright of Met Geo Environmental Limited. Disclosure of this information to Third Parties and unauthorised copying or replication of this data without approval is forbidden.

Direction of North


Grid : OS National Grid.
Using the OS GPS Network and applying OSTN02 transformation and then removing the scale factor for true distances with a one-step transformation centred on S1

Datum : OS Level Datum.
Using the OS GPS Network and applying OSGM02 National Geoid Model to obtain local area corrections.

Station Listing

| Station | Easting | Northing | Level |
|---|---|---|---|
| A1 | 434480.223 | 406366.619 | 99.083 |
| A2 | 434543.374 | 406401.407 | 98.570 |
| A3 | 434555.848 | 406351.428 | 96.595 |
| AL1 | 434820.135 | 406276.451 | 90.051 |
| AS2 | 434783.892 | 406202.243 | 93.553 |
| AS10 | 434481.713 | 406367.188 | 99.082 |
| AU1 | 434592.173 | 406271.197 | 96.573 |
| AU2 | 434651.825 | 406212.272 | 101.217 |
| AU3 | 434673.007 | 406228.703 | 101.264 |
| AU5 | 434583.018 | 406402.709 | 97.731 |
| AU6 | 434705.938 | 406351.908 | 97.051 |
| AU7 | 434662.977 | 406325.614 | 97.267 |
| AU8 | 434778.467 | 406362.073 | 91.527 |
| AU10 | 434628.242 | 406343.265 | 96.640 |
| AU11 | 434653.254 | 406310.545 | 97.255 |
| AU12 | 434681.216 | 406411.276 | 94.093 |
| AU8A | 434660.035 | 406352.906 | 96.882 |
| AU6B | 434652.642 | 406319.082 | 97.147 |
| AU7C | 434681.519 | 406355.646 | 97.018 |
| C1 | 434712.462 | 406225.869 | 96.623 |
| C2 | 434727.503 | 406419.334 | 93.150 |
| C3 | 434721.679 | 406372.200 | 92.690 |
| C4 | 434735.914 | 406359.097 | 91.234 |
| C5 | 434743.584 | 406331.452 | 91.022 |
| G1 | 434753.750 | 406274.067 | 94.375 |
| RM1 | 434632.277 | 406193.847 | 96.823 |
| RM2 | 434663.232 | 406464.517 | 95.546 |
| RM3 | 434598.707 | 406431.132 | 97.781 |
| RM4 | 434637.041 | 406534.940 | 97.076 |
| RM5 | 434646.151 | 406488.039 | 96.047 |
| RM6 | 434752.985 | 406409.662 | 92.882 |
| RM7 | 434822.485 | 406411.081 | 92.832 |
| S1 | 434625.882 | 406225.994 | 97.326 |
| S2 | 434562.494 | 406300.082 | 96.717 |
| S3 | 434500.632 | 406339.004 | 97.937 |
| S4 | 434591.352 | 406337.611 | 95.950 |
| S5 | 434462.262 | 406339.104 | 98.714 |
| S6 | 434412.220 | 406315.767 | 100.782 |
| SD1 | 434693.601 | 406357.827 | 96.797 |
| SD2 | 434704.574 | 406374.384 | 95.560 |
| AB1 | 434696.602 | 406372.204 | 96.130 |
| AB2 | 434641.029 | 406399.385 | 95.383 |
| AB3 | 434597.715 | 406380.763 | 96.821 |
| SC1 | 434675.386 | 406393.671 | 94.894 |
| SC2 | 434638.179 | 406374.356 | 96.690 |

Layout Key




KEY

| | | | |
|---|---|---|---|
| AIR VALVE | AV | JUNCTION BOX | JU BOX |
| BENCH MARK | BM | KERB OUTLET | KO |
| BIN | BIN | LAMP POST | LP |
| BOLLARD | BOL | MANHOLE (CIRCULAR) | MH |
| BORE HOLE | BH | MANHOLE (RECTANGULAR) | MH |
| BRITISH TELECOM COVER | BT | MANHOLE (TRIANGULAR) | MH |
| BUS STOP | BUS | MARKER POST | MARK |
| CABLE TV COVER | CATV | GULLY | GU |
| CABLE TV SUPPLY | CTS | RODDING EYE | RE |
| COLUMN | COL | SIGN POST | SIGN |
| EARTHING POINT | ER | TELECOM COVER | TC |
| ELECTRICITY COVER | ELEC | TELEGRAPH POLE | TP |
| ELECTRICITY POLE | EP | THRESHOLD LEVEL | TH |
| FIRE HYDRANT | FH | TRAFFIC LIGHT | TL |
| GAS VALVE | GAS | TRIAL PIT | TP |
| GATE | G | WASH OUT | WO |
| INSPECTION COVER (CIRCULAR) | IC | WATER METER | WM |
| INSPECTION COVER (RECTANGULAR) | IC | WATER STOP COCK | SC |
| | | WATER STOP VALVE | SV |
| COVER LEVEL | CL | | |
| INVERT LEVEL | IL | CHAMBER BASE LEVEL | Ch.L |
| UNABLE TO RAISE | UTR | WATER SURFACE LEVEL | WL |
| GIRTH OF TREE TRUNK | G | UNABLE TO MEASURE | U/M |
| HEIGHT TO TOP OF TREE CANOPY | H | DIAMETER OF TREE TRUNK | D |
| | | MULTI BOLE TREE | MB |

| Rev | Date | Drawn | Description | Check |
|---|---|---|---|---|
| A | 23/03/2016 | MD | SURVEY DEMOLITION AREA | DA |

Met GEO ENVIRONMENTAL
Southgate House
Pontefract Road
Stourton
Leeds
West Yorkshire
LS10 1SW
T: +44 [0] 1132 008 900
F: +44 [0] 1132 008 901
E: admin@metgeoenvironmental.com
W: www.metgeoenvironmental.com

Client
NPS GROUP

Site
BARNSLEY TOWN CENTRE
BARNSLEY, SOUTH YORKSHIRE

Title
TOPOGRAPHICAL SURVEY
2D

| | | | |
|---|---|---|---|
| Surveyed | RM, CC, AS, AU, SD, GP, AL | Drawn | RM, CC, AS, AU, SD |
| Chk. | CC | Date | 02/07/2014 |
| Scale | 1/200 | DWG Ref (Layout No) | 11549-201_2DT(2) |
| | (A0 Sheet) | | Status: REV |
| Job No | 11549-201-4 | | Rev: A |