CONTROL COORDINATE SCHEDULE (OSGB36)			
STATION	EASTING	NORTHING	HEIGHT
AGPS	437236.506	409928.654	50.497
BGPS	437245.450	410010.597	50.633

Dense Vegetation
MH CL: 49.69
Unable to survey due to excessive depth.
AGPS
Unable to ascertain depth of service.
Dense Vegetation
Fence
Tree
Grass
Unable to detect further due to dense vegetation.
Unable to survey due to dense vegetation.
Dense Vegetation
Gate
Unable to detect further due to dense vegetation.
Grass
Unable to ascertain depth of service.
Dense Vegetation
Unable to survey due to ground condition.
ACCESS ROAD
Unable to ascertain depth of service.
Dense Vegetation

LEGEND

- Scan Area
- Radio Frequency Scan Area
- Previous Scan Area
- Electricity Cable
- Street Lighting
- Power Carrying Feature
- Telecommunication Cable
- Cable Television Cable
- Closed Circuit Television Cable
- Traffic Signalling
- Alarm Cable
- Telemetry Cable
- Fibre Optic Cable
- Energis Cable
- Unknown Cable
- Empty Duct
- Foul Water Sewer
- Surface Water Drain
- Combined Sewer
- Culvert
- Water Pipe
- Fire Main
- Gas Pipe
- Oil Pipe
- Fuel Main
- Steam Pipe
- Vent Pipe
- Unknown Pipe
- Earth Strap
- Metallic Feature
- Detected Linear Feature
- Possible Linear Feature
- Taken from Statutory Information
- (Applicable to any service)
- (Applicable to any service)
- Assumed
- Anomalous Area
- Area of Radio Frequency Disturbance
- Area of Electrical Interference
- Area of Reinforcing
- Chamber
- Unable to Survey

ABBREVIATIONS (where applicable)

AV	Air Valve	LP	Lamp Post
BB	Belisha Beacon	MH	Manhole
BC	Bottom of Chamber	MKR	Marker
BH	Borehole	P	Post
BOL	Bollard	RE	Rodding Eye
BT	British Telecom Cover	RG	Rain Gully
CAB	Cabinet	RS	Road Sign
CATV	Cable Television Cover	SP	Sign Post
CCTV	Closed Circuit TV	ST	Stop Tap
CL	Cover Level	STN	Survey Station
DIA	Diameter	SV	Sluice Valve
DP	Down Pipe	TC	Top of Chamber
EP	Electricity Pole	TCB	Telephone Call Box
ER	Earth Rod	TL	Traffic Light
FH	Fire Hydrant	TP	Telegraph Pole
GV	Gas Valve	UTL	Unable to Lift
IC	Inspection Cover	VP	Vent Pipe
IL	Invert Level	WM	Water Meter
IRS	Illuminated Road Sign	WO	Wash Out
JB	Junction Box		

NOTES

Depending on their individual suitability, a variety of detection methods were applied using all reasonable skill and care, in order to obtain the underground information needed to produce these survey results.

Variations in ground conditions, density of services and/or other external influences may affect the accuracy of the data recorded for this non-invasive survey. The detection and accuracy of any subsurface feature detected using non-invasive techniques is not guaranteed.
ALWAYS EXERCISE CAUTION WHEN EXCAVATING.

Underground services shown on this drawing are illustrated by an individual service line. This does not necessarily represent number of cables and/or ducts.

Depths shown are to top of service or feature unless otherwise stated. Generally +/- 10% of the detected feature depth, in both the vertical and horizontal planes. All depths obtained both through direct measurement and non-invasive detection are as accurate as can be achieved at the time of survey.


Pipe sizes are shown only from visual inspection or taken from statutory records.

The definition of an anomalous area is an area where the radar data shows a substantial change in uniform data from its surrounding area. These areas could be voids, heavily saturated ground, buried tanks or other subsurface features.

Unless otherwise stated all coordinates and levels are related to OSGB36 datum by GPS.

IF IN DOUBT ASK

SHEET LAYOUT



GEOTEC
underground mapping

GEOTEC SURVEYS LIMITED
PO Box 99, Godalming, Surrey, GU7 2XT
TEL: 01428 686168 EMAIL: geotec@geotecsurveys.com
FAX: 01428 686169 WEB: www.geotecsurveys.com

Client:	Site:
Photon Energy Ltd 8 Windsor Square Silver Street Reading RG1 2TH	Premier Foods Barnsley S71 3HF
Project No: 2304s021	Date: April 2023
Sheet No: 7 of 7	Scale: A0 Sheet @ 1:100
Drawn by: CS	Approved by: LH

Revision	Details	Initial	Date

Scale bar
0.0m 1.0m 2.0m 3.0m 4.0m 5.0m 6.0m 7.0m 8.0m 9.0m 10.0m