

**PROPOSED COSMETIC INTERNAL UPGRADE AND
INSTALLATION OF LOW LEVEL RAILINGS TO 5 NO. EXTERNAL
GROUND FLOOR WINDOWS FOR:**

YORKSHIRE BANK TO THEIR BRANCH AT:

1A PEEL SQUARE, BARNSELY, SOUTH YORKSHIRE, S70 2PL.

DOCUMENT REF: 2058/54/PH01


**EXISTING PHOTOGRAPHS OF EXTERNAL ELEVATIONS &
GROUND FLOOR WINDOWS**

DATE: MARCH 2015. REV: '0'.

VAUGHAN MONCKTON ARCHITECTURE LTD



1) CORNER ENTRANCE



2) CORNER ENTRANCE




3) VIEW UP MARKET HILL




4) WINDOW 'BOTTOM' UP MARKET HILL




5) window 'Bottom' up market hill



6) window Bottom adjacent to back door




7) Tenant Door & Elevation to Market Hill



8) 2 no windows adjacent Entrance



9) HIGH LEVEL ADJACENT CORNER




10) DOOR JAMB TO MAIN ENTRANCE



11) 1st window BAY TO PEEL SQUARE



12) HIGH LEVEL TO PEEL SQUARE




13) 'ATMS' ON PEELE SQUARE



14) WINDOW BARS ON PEELE SQUARE



15) EXTENT OF DAMAGE TO PEELE SQ.



16) ELEVATION TO PEELE SQ. ADJACENT ENTRANCE



17) WINDOW SILL AT NIGHTSAFE LOCATION



18) ENLARGED VIEW AROUND NIGHTSAFE




19) EXAMPLE OF PREVIOUS WORK / MAKING GOOD



20) WINDOW SILL ADJACENT ENTRANCE TO PEEL SQUARE



21) LOW LEVEL DETAIL ON PEEL
SQUARE ADJACENT ENTRANCE



22) ENTRANCE DOOR THRESHOLDS
ON 'CURVED'.