

# Trial Pit Photos

TP02

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 19: TP02 arisings. (5).



Met Consultancy Group Ltd  
 Southgate House  
 Pontefract Road  
 Leeds  
 LS10 1SW  
 Email: admin@metconsultancygroup.com  
 Phone: 0113 200 8900

# Trial Pit Log

TrialPit No  
 TP03  
 Sheet 1 of 1

Project Name: Parkside Sports and Community Centre, Hoyland  
 Project No. P22-01115  
 Co-ords: 435931.97 - 399795.22  
 Level:  
 Date: 16/12/2022

Location: Land between Sheffield Road and Stead Lane, Hoyland, Barnsley, S74 0AH  
 Dimensions (m): 7.50  
 Scale: 1:25

Client: Barnsley Metropolitan Borough Council  
 Depth: 2.80  
 Logged: YK

Water Strike	Samples & In Situ Testing			Depth (m)	Level (m)	Legend	Stratum Description
	Depth	Type	Results				
				0.30			Grass overlying dark brown silty slightly sandy slightly gravelly CLAY (TOPSOIL). Metal wires and fragments of wood noted.
				1.40			Reowrked oangish brown silty sandy slightly gravelly CLAY. Sand is fine to coarse. Gravel is angular to subangular fine to coarse of sandstone and siltstone.
				2.80			Orangish brown mottled grey silty sandy gravelly CLAY with a moderate cobble content. Sand is fine to coarse. Gravel is angular to subangular fine to coarse of sandstone and siltstone. Cobbles are angular to subangular of sandstone/siltstone up to 100mm across. Probably completely weathered bedrock.
				2.80			Brown SILTSTONE/SANDSTONE bedrock. Trial pit extended to the south to identify any potential high wall. A 0.4-0.5m thick lens of opencast fill material comprising grey cobbles and boulders up to 1.5m across in a sand and gravel matrix identified at a top depth of 1.0mbgl. As trial pit progresses, this opencast fill material becomes deeper until it is recorded directly overlying bedrock. No high wall identified. End of Pit at 2.80m

Remarks: Trial pit terminated on siltstone/sandstone bedrock.

Stability: Unstable due to opencast backfill. Weather: Clear

# Trial Pit Photos

TP03

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 20: Trial pit TP03. Northern face of trial pit, view from the south east to the north west.



Photograph 21: Trial pit TP03. Western side of trial pit, view from the north east to the south west.

# Trial Pit Photos

TP03

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 22: Trial pit TP03. Eastern side of trial pit, view from the north west of the south east.



Photograph 23: Trial pit TP03. Southern face of trial pit, view from the north to the south.

# Trial Pit Photos

TP03

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 24: TP03 arisings. (1).



Photograph 25: TP03 arisings. (2).

# Trial Pit Photos

TP03

Parkside Sports and  
Community Centre, Hoyland

P22-01115



Photograph 26: TP03 arisings. (3).



Photograph 27: TP03 arisings. (4).